

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	6/10/2026	Time:	8:41 AM
Name of School Corporation:	MILLER TRANSPORTATION	Corp ID:	49022Z		
Address of School Corporation:	1103 S Tibbs Avenue				
City:	Indianapolis	Zip:	46241	County Number:	49
VIN:	4DRBUC8N1NB419464	License Number:	B584T	Bus Number:	2062
Make of Body:	IC Corporation	Year:	2021	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	113649	Year:	2022
Inspection Status:	O	Inspected By:	Nathan Hampton	PE:	8616

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
70-1-4	There is any cracked glass to the immediate right or left of the driver
51-1-4	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
22-1-1	A dripping oil or fluid leak
57-1-2	Step-well area is weakened
53-1-1	One (1) leaf spring is broken under the first two (2) leaves
36-1-2	The latch is not properly aligned, is loose or badly rusted

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
63-2-3	Any tire is flat
55-2-3	Any steering component jams or inhibits safe movement
30-2-1	Floor sags or buckles substantially when stood upon. (NOTE: Check under bus to verify deterioration.)
31-2-1	Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.