# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 6/17/2026 | **Time:** | 9:52 AM |
| **Name of School Corporation:** | SOUTH PUTNAM COMMUNITY SCHOOLS | | | **Corp ID:** | 676705 |
| **Address of School Corporation:** | 3999 S US 231 | | | | |
| **City:** | Greencastle | **Zip:** | 46135 | **County Number:** | 67 |
| **VIN:** | 1GBJG31K891152556 | **License Number:** | 82840 | **Bus Number:** | 1033 |
| **Make of Body:** | Chevrolet **Year:** 2009 | **Make of Chassis:** | Chevrolet | **Year:** | 2009 |
| **Bus Type:** | | **Mileage:** | 91199 | | |
| **Inspection Status:** | R | **Inspected By:** | Tyler VanNess | **PE:** | 7583 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 17-1-1 | Any dome light is inoperative |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type Description |
|---|