

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/29/2026	Time: 10:24 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE)	Corp ID: 251807	
Address of School Corporation: 11260 Cornell Park Dr Suite 700		
City: Cincinnati	Zip: 45242	County Number: 18
VIN: 4DRBUC8P5JB593436	License Number: B611T	Bus Number: M36
Make of Body: IC Corporation	Year: 2016	Make of Chassis: IC Corporation
Bus Type: C	Mileage: 79794	Year: 2018
Inspection Status: R	Inspected By: Eric Parker	PE: 7297

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.