

## REPORT OF SCHOOL BUS INSPECTION

|                                |                          |                 |                |                  |                          |       |      |
|--------------------------------|--------------------------|-----------------|----------------|------------------|--------------------------|-------|------|
| Type of Inspection:            | Annual                   | Date:           | 7/9/2026       | Time:            | 9:03 AM                  |       |      |
| Name of School Corporation:    | WAWASEE COMMUNITY SCHLS  |                 |                | Corp ID:         | 434345                   |       |      |
| Address of School Corporation: | 1 Warrior Path Bldg 2    |                 |                |                  |                          |       |      |
| City:                          | Syracuse                 | Zip:            | 46567          | County Number:   | 43                       |       |      |
| VIN:                           | 1GB3GSB77N1171980        | License Number: | 94602          | Bus Number:      | 92                       |       |      |
| Make of Body:                  | Thomas Built Buses, Inc. | Year:           | 2022           | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2022 |
| Bus Type:                      | A1                       | Mileage:        | 53479          |                  |                          |       |      |
| Inspection Status:             | R                        | Inspected By:   | Travis Harrold | PE:              | 8022                     |       |      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                                                                  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| 23-1-3                 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type A School Bus** - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.