

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/24/2026	Time:	12:07 PM		
Name of School Corporation:	EAST NOBLE SCHOOL CORPORATION			Corp ID:	576060		
Address of School Corporation:	126 W Rush St						
City:	Kendallville	Zip:	46755	County Number:	57		
VIN:	4UZABRFC8VCWR4989	License Number:	28881	Bus Number:	27		
Make of Body:	AmTran	Year:	2026	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2027
Bus Type:	C	Mileage:	3642				
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
20-2-2	Door glass is missing
20-2-4	Emergency door is not securely fastened to body
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.