

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/9/2026	Time:	5:01 PM
Name of School Corporation:	CONCORD COMMUNITY SCHOOLS	Corp ID:	202270		
Address of School Corporation:	59040 Minuteman Way				
City:	Elkhart	Zip:	46517	County Number:	20
VIN:	1BABNBPA0GF315354	License Number:	9406	Bus Number:	9
Make of Body:	Blue Bird Corporation	Year:	2014	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	108502	Year:	2015
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-1	The front bumper does not extend to the edge of the fenders

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.