

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 9/10/2026	Time: 11:06 AM
Name of School Corporation: OAK FARM MONTESSORI SCHOOL	Corp ID:	
Address of School Corporation: 502 Lemper Road		
City: Avilla	Zip: 46710	County Number: 57
VIN: 1BAKGCPA5DF290883	License Number: B502X	Bus Number: 72
Make of Body: Blue Bird Corporation	Year: 2012	Make of Chassis: Blue Bird Corporation
Year: 2013	Year: 2013	
Bus Type: C	Mileage: 70852	
Inspection Status: O	Inspected By: Joseph Hartman	PE: 7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-5	Any paint is badly faded or peeling
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)
89-1-2	The strobe light is not white
89-1-3	The strobe light is inoperative
43-1-8	Any required lettering is missing or faded.
15-1-1	The defroster system is not working properly.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
41-1-9	See Notes: Any defect inspector deems a violation not listed
68-1-1	Washers do not function properly in any manner

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.