

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/22/2026	Time: 10:22 AM
Name of School Corporation: M.S.D. MARTINSVILLE SCHOOLS	Corp ID: 555925	
Address of School Corporation: PO Box 1416		
City: Martinsville	Zip: 46151	County Number: 55
VIN: 4UZABRFC0SCUS7678	License Number: 27096	Bus Number: 50
Make of Body: Freightliner	Year: 2024	Make of Chassis: Thomas Built Buses, Inc.
Bus Type: C	Mileage: 19221	Year: 2025
Inspection Status: O	Inspected By: Mike Adams	PE: 7407

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)
57-1-5	Step-well light is missing or inoperative
57-1-4	Grab handle is loose or missing
23-1-1	Any part is missing, including originally equipped heat shields
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
7-1-3	Air leak at proper connection
34-1-1	Any headlight is inoperative
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
4-1-1	Any body clamp is loose.
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
53-1-1	One (1) leaf spring is broken under the first two (2) leaves
61-1-4	There is an air leak from any hose, line, tank, bag, or other component of an air suspension system
61-1-2	Vertical or horizontal ball joint movement is more than 1/8 inch but less than 1/4 inch
59-1-1	The stop arm lights do not flash alternately
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
52-1-1	There are any loose, broken, or missing mountings
31-1-1	There are loose or missing bolts or rivets where front and rear spring hangers are attached to the frame
25-1-2	Mirrors do not meet minimum specifications for indirect visibility as set out in Indiana's minimum specifications for school buses
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

24-2-1

14-2-1

Any crossmember is cracked or broken

31-2-1

Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.