

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/29/2026	Time:	12:47 PM
Name of School Corporation:	M.S.D. WARREN TWP.	Corp ID:	495360		
Address of School Corporation:	9150 Rawles				
City:	Indianapolis	Zip:	46229	County Number:	49
VIN:	4DRBUP1N1PB106662	License Number:	25723	Bus Number:	139
Make of Body:	IC Corporation	Year:	2022	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	41638	Year:	2023
Inspection Status:	O	Inspected By:	Kyle Parton	PE:	9108

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
82-1-2	See Notes: Any defect inspector deems a violation not listed
20-1-5	Door glass is chipped, or cracked
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
22-1-1	A dripping oil or fluid leak
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
64-1-2	A lens is cracked, missing or wrong color
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
16-2-1	When any wheel seal is leaking and includes evidence of wet contaminated brake friction material and accompanied by evidence that further leaking will occur.
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.