REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	9/29/2026	**Time:**	12:47 PM
Name of School Corporation:	M.S.D. WARREN TWP.			**Corp ID:**	495360
Address of School Corporation:	9150 Rawles				
City:	Indianapolis	**Zip:**	46229	**County Number:**	49
VIN:	4DRBUP1N1PB106662	**License Number:**	25723	**Bus Number:**	139
Make of Body:	IC Corporation **Year:** 2022	**Make of Chassis:**	IC Corporation	**Year:**	2023
Bus Type:	C	**Mileage:**	41638		
Inspection Status:	O	**Inspected By:**	Kyle Parton	**PE:**	9108

Violations - Rejected

Inspection Code	Description
82-1-2	See Notes: Any defect inspector deems a violation not listed
20-1-5	Door glass is chipped, or cracked
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
22-1-1	A dripping oil or fluid leak
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
64-1-2	A lens is cracked, missing or wrong color
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver

Violations - Out of Service

Inspection Code	Description
16-2-1	When any wheel seal is leaking and includes evidence of wet contaminated brake friction material and accompanied by evidence that further leaking will occur.
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.