

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/9/2026	Time:	9:06 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	1BAKFCKH25F229144	License Number:	B896D	Bus Number:	18
Make of Body:	Blue Bird Corporation	Year:	2004	Make of Chassis:	Chevrolet
Bus Type:	C	Mileage:	136310	Year:	2005
Inspection Status:	O	Inspected By:	Brent Hoover	PE:	7562

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
40-1-1	Any required instrument or gauge is missing. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)
40-1-3	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.