REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	**Date:**	10/20/2026	**Time:**	9:35 AM
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS			**Corp ID:**	475075
Address of School Corporation:	595 Stars Blvd				
City:	Bedford	**Zip:**	47421	**County Number:**	47
VIN:	4DRBUAAN9EB795232	**License Number:**	6573	**Bus Number:**	52
Make of Body:	IC Corporation **Year:** 2013	**Make of Chassis:**	IC Corporation	**Year:**	2014
Bus Type:	C	**Mileage:**	152279		
Inspection Status:	O	**Inspected By:**	Zach Ruble	**PE:**	7715

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
65-2-3	There is not 2 amber and 2 red seven inch rear warning lamps horizontally mounted at least 60” apart above the top of the side windows. (Amber lights must be mounted in between the red)

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.