REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	11/4/2026	**Time:**	12:14 PM
Name of School Corporation:		AUXILIO SERVICES (MUNCIE)				**Corp ID:**	251807
Address of School Corporation:		11260 Cornell Park Dr Suite 700					
City:	Cincinnati	**Zip:**	45242			**County Number:**	18
VIN:	4UZABRDT4HCJD4275			**License Number:**	B534N	**Bus Number:**	M27
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2018	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2017
Bus Type:	C			**Mileage:**	82140		
Inspection Status:	O	**Inspected By:**	Eric Parker			**PE:**	7297

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
53-2-5	“U” bolts are loose, broken, or missing
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.