## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 1/3/2012 Time: 11:45 AM Name of School Corporation: DALEVILLE COMMUNITY SCHOOLS Corp ID: 181940

Address of School Corporation: 14300 W 2nd St

City:DalevilleZip:47334County Number:18VIN:1HVBBABN9WH567474License Number:16618Bus Number:2Make of Body:Carpenter Year:1999Make of Chassis:IC Corporation Year:1999

Bus Type: C Mileage: Unknown

Inspection Status: R Inspected By: Brian Bills PE: 5506

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u> 42-1-2 Floor covering is missing, cut, loose, buckled or bulging.

42-1-4 Prohibited area line is missing or improper.

34-1-1 There is significant engine oil or fluid leak from the engine.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.