REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	1/6/2012	**Time:**	8:56 AM
Name of School Corporation:		RICHLAND-BEAN BLOSSOM C.S.CORP				**Corp ID:**	535705
Address of School Corporation:		600 S Edgewood Dr					
City:	Ellettsville	**Zip:**	47429			**County Number:**	53
VIN:	4UZABRDT09CAE8286			**License Number:**	B326E	**Bus Number:**	9
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2009	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2009
Bus Type:	C			**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Mark Raper			**PE:**	6473

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
46-2-1	There is a fuel leak from any line, connection or fitting.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.