

# REPORT OF SCHOOL BUS INSPECTION

|                                |                              |                   |              |                  |                |
|--------------------------------|------------------------------|-------------------|--------------|------------------|----------------|
| Type of Inspection:            | Semi-Annual                  | Date:             | 1/9/2012     | Time:            | 3:51 PM        |
| Name of School Corporation:    | NORTHERN WELLS COMM. SCHOOLS |                   |              | Corp ID:         | 908435         |
| Address of School Corporation: |                              |                   |              |                  |                |
| City:                          | Zip:                         | County Number: 90 |              |                  |                |
| VIN:                           | 1HVBBABN7WH572575            | License Number:   | 4219         | Bus Number:      | 31             |
| Make of Body:                  | AmTran                       | Year:             | 1998         | Make of Chassis: | IC Corporation |
| Bus Type:                      | C                            | Mileage:          | Unknown      | Year:            | 1998           |
| Inspection Status:             | R                            | Inspected By:     | Tom Merkling | PE:              | 5390           |

## Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 86-1-2                 | The light is of an improper color   |
| 93-1-4                 | Any front turn signal does not function properly                                    |
| 63-1-1                 | The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49. |
| 53-1-1                 | A heater motor is inoperative at any speed.   |

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.