

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-------------------------|------------------------|----------------|-------------------------|-----------------------|
| Type of Inspection: | Semi-Annual | Date: | 1/10/2012 | Time: | 11:42 AM |
| Name of School Corporation: | BAUGO COMMUNITY SCHOOLS | | | Corp ID: | 202260 |
| Address of School Corporation: | 29125 CR 22 W | | | | |
| City: | Elkhart | Zip: | 46517 | County Number: | 20 |
| VIN: | 1BAKJCPA3BF278679 | License Number: | 859 | Bus Number: | 13 |
| Make of Body: | Blue Bird Corporation | Year: | 2011 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | C | Mileage: | Unknown | Year: | 2011 |
| Inspection Status: | O | Inspected By: | Travis Harrold | PE: | 8022 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 99-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |
| 36-1-5 | Any hanger, clamp or bracket is missing, loose or broken. |
| 34-1-1 | There is significant engine oil or fluid leak from the engine. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.