

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	1/11/2012	<b>Time:</b>	8:54 AM
<b>Name of School Corporation:</b>	OAK HILL UNITED SCHOOL CORP.	<b>Corp ID:</b>	525625		
<b>Address of School Corporation:</b>	PO Box 550				
<b>City:</b>	Converse	<b>Zip:</b>	46919	<b>County Number:</b>	52
<b>VIN:</b>	4UZABRDT0CCBA1334	<b>License Number:</b>	1284	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2012	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body.
30-1-5	Door glass is cracked or chipped.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**