

STATE OF INDIANA

INDIANA UTILITY REGULATORY COMMISSION

IN	THE	MATTER	OF	$\mathbf{A}\mathbf{N}$	ORDER)		
API	PROVIN	IG ADVISO	ORY	COM	IMITTEE)	APPROVED:	JUL 3 1 2013
REC	COMMI	ENDATIONS	Pl	URSUA	ANT TO)		DOL O T. COLD
IND	IANA C	CODE CHAP	TER 8	-1-26.)		

ORDER OF THE COMMISSION

Indiana Code chapter 8-1-26 provides the procedure for the Indiana Utility Regulatory Commission's Pipeline Safety Division ("Division") to find violations of said chapter. Upon review of those findings, the Indiana Underground Plant Protection Advisory Committee ("Advisory Committee") reviews those recommendations and recommends civil penalties in the Case.

The Cases received pursuant to Indiana Code chapter 8-1-26 and ripe for Commission action are attached hereto and collectively referred to as the Advisory Committee Recommendations.

Pursuant to statute, the Advisory Committee has submitted their recommendations to the Commission. The Commission hereby UPHOLDS the findings of violations by the Pipeline Safety Division and APPROVES the recommendations of the Advisory Committee as listed on the attached pages. The Assistant General Counsel to the Division is hereby directed to prepare and send notice to the parties advising them of the determination.

IT IS SO ORDERED.

ATTERHOLT, BENNETT, LANDIS, MAYS AND ZIEGNER CONCUR; MAYS NOT PARTICIPATING IN THOSE MATTERS INVOLVING VECTREN:

APPROVED:

JUL 3 1 2013

I hereby certify that the above is a true and correct copy of the Order as approved.

Brenda A. Howe

Secretary to the Commission

Case	Excavator Name	Penalty	Committee	Date of
No.			Date	Damage
4366	Bender Construction Inc.	Warning Letter	21-May-13	17-Oct-12
4079	BENDER UNDERGROUND CONSTRUCTION	Warning Letter	23-Apr-13	30-Oct-12
4309	BENJAMIN FRANKLIN PLUMBING	Warning Letter	21-May-13	02-Jan-13
3572	BENNETTS PLU MBING	Warning Letter	26-Feb-13	15-Aug-12
3515	BERRY-IT, INC.	Training 1st Level	26-Feb-13	27-Jul-12
2942	BERRY-IT, INC.	Warning Letter	28-Aug-12	09-May-12
2186	BETH OLS	Warning Letter	30-May-12	09-Oct-11
27	Billy Joe Bebout	Warning Letter	28-Feb-12	03-Jun-10
843	BINCON CONSTRUCTION	Warning Letter	24-Jan-12	03-Feb-10
4260	BLANKENBERGER BROTHERS	Warning Letter	21-May-13	04-Dec-12
1087	BLAZER FARMS	Warning Letter	27-Mar-12	29-Jul-10
3989	BLUFFTON Water Department	Warning Letter	23-Apr-13	03-Oct-12
3482	B-Mac Wireless Inc	Warning Letter	26-Feb-13	30-Jul-12
3697	BOB BUESCHER HOMES	Warning Letter	26-Mar-13	31-Aug-12
4190	Bob Workman	Warning Letter	23-Apr-13	03-Oct-12
1292	BORE-IT	Warning Letter	30-May-12	25-Oct-10
3051	Borgmann Family Enterprises	Warning Letter	28-Aug-12	10-May-12
3758	BOWEN CONSTRUCTION	Warning Letter	21-May-13	12-Jul-12
3251	Brackney, Inc.	Warning Letter	28-Aug-12	01-May-12
437	BRADS-KO ENGINEERING AND SURVEYING, INC.	Warning Letter	28-Feb-12	25-May-11
2163	BRETT LAMBERT	Warning Letter	30-May-12	01-Oct-11
396	BRIAN CROSSWAITHE	Warning Letter	30-May-12	12-May-11
3568	BRIAN OTTEN	Warning Letter	27-Nov-12	15-Aug-12
2697	BRIAN PFAEHLER	Warning Letter	26-Jun-12	18-Jan-12
1954	BRIENNE MEEHAN	Warning Letter	30-May-12	07-Aug-11
3964		Warning Letter	26-Mar-13	10-Sep-12
3672	BRYAN POWERS	Warning Letter	26-Feb-13	26-Aug-12
3086		Warning Letter	25-Sep-12	05-Jun-12
3910		Warning Letter		26-Aug-12
1613		Warning Letter	28-Feb-12	19-Oct-10
787	- · · · · · · · · · · · · · · · · · · ·	Warning Letter	30-May-12	23-Nov-09
2998		Warning Letter	24-Jan-13	24-May-12
3239		Warning Letter		01-May-12
3185		Warning Letter		14-Jun-12
73		Warning Letter		22-Mar-11
1063		Warning Letter		25-Oct-12
3517		Warning Letter		28-Jul-12
3116		Training 1st Level		29-May-12
113		Warning Letter	26-Jun-12	18-May-11
		Warning Letter		23-Aug-10
		Warning Letter		16-Sep-10
		Warning Letter		10-Sep-10 10-Dec-12
		Training 1st Level		26-Nov-12
144U ·		Training 1st Level		27-Nov-12
12/1/1			ZITIVIAVELD 1	∠/-INUV-TZ
	-	Warning Letter		11-Sep-12

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
3455	Castleman Septic Systems & Sewers	Training 1st Level	24-Jan-13	11-Jul-12
3441	Castleman Septic Systems & Sewers	Warning Letter	27-Nov-12	15-Jun-12
3756	CC&T Construction Inc	Training 1st Level	26-Feb-13	14-Jun-12
3075	CC&T CONSTRUCTION INC	Warning Letter	25-Sep-12	13-Jun-12
3634	CCI (Campbell Cruze, Inc.)	Warning Letter	27-Nov-12	25-Jul-12
3310	CCT UNDERGROUND LLC	Warning Letter	26-Mar-13	03-Jul-12
2957	CENTURYLINK	Warning Letter	28-Aug-12	14-May-12
1571	Charles Chanley Jr	Warning Letter	30-May-12	11-Jul-10
3064	CHARLES L BECK	Warning Letter	25-Sep-12	11-Jun-12
1052	Chipman's Maintenance	Warning Letter	19-Apr-12	14-Jul-10
1204	CHRIS BOWMAN	Warning Letter	28-Feb-12	04-Sep-10
3632	CHRIS SMITH	Warning Letter	24-Jan-13	26-Aug-12
30	Christian Roll	Warning Letter	19-Apr-12	11-Oct-10
3460	Christopher Baker	Warning Letter	26-Feb-13	03-Jul-12
3960	Christopher Brown	Warning Letter	26-Mar-13	11-Sep-12
1092	CIRCLE R ELECTRIC	Warning Letter	27-Mar-12	30-Jul-10
857	CITY LIGHTS AND SIGNALS	Warning Letter	30-May-12	06-Mar-10
3252	City of Attica	Warning Letter	25-Sep-12	12-Jun-12
3955	City of Berne Water Department	Warning Letter	26-Mar-13	14-Sep-12
2928	CITY OF BLUFFTON PARKS DEPARTMENT	Warning Letter	28-Aug-12	07-May-12
3641	City of Columbia City - Electric Division	Warning Letter	27-Nov-12	02-Aug-12
1143	CITY OF ELKHART	Warning Letter	30-May-12	16-Aug-10
1740	CITY OF ELKHART	Warning Letter	30-May-12	15-Feb-11
3652	City of Fort Wayne Utilities	Warning Letter	26-Feb-13	07-Aug-12
3661	City of Hammond Water Dept.	Warning Letter	27-Nov-12	02-Aug-12
1524	City of Jasper	Warning Letter	30-May-12	14-Aug-09
1957	CITY OF LAKE STATION SEWER DEPARTMENT	Warning Letter	30-May-12	08-Aug-11
3727	City of Mishawaka	Warning Letter	26-Feb-13	18-Jun-12
1991	CITY OF PLYMOUTH STREET DEPARTMENT	Warning Letter	19-Apr-12	16-Aug-11
1550	City of Rising Sun	Warning Letter	24-Jan-12	16-Oct-09
3943	City of South Bend Sewer Department	Training 1st Level	26-Mar-13	31-Aug-12
3500 .	City of South Bend Sewer Department	Warning Letter	24-Jan-13	29-Jun-12
3203	CITY OF VALPARAISO SEWER DEPARTMENT	Warning Letter	23-Oct-12	19-Jun-12
75	Clint Guthrie	Warning Letter	28-Feb-12	30-Mar-11
57	Clint Novak	Warning Letter	28-Feb-12	08-May-10
3103	Clyde Bradley	Warning Letter	25-Sep-12	29-May-12
3129	COLUMBIA CITY WATER DEPARTMENT	Warning Letter	28-Aug-12	05-Jun-12
1141	COMMUNITY BAPTIST CHURCH	Warning Letter	19-Apr-12	13-Aug-10
3924	Concrete Constructors Inc	Warning Letter	26-Mar-13	03-Aug-10
429	CONCRETE TECH	Warning Letter	27-Mar-12	23-May-11
3625	Coor Consulting and Land Services Corp.	Warning Letter	24-Jan-13	20-Aug-12
3478	Creek Enterprises, Inc.	Warning Letter	26-Feb-13	09-Jul-12
3099	Cripe Excavating	Training 1st Level	25-Feb-13 25-Sep-12	08-May-12
3099	Cripe Excavating Cripe Excavating	Warning Letter	28-Aug-12	26-Jun-12
1773	CROSBY EXCAVATING INC.	Warning Letter	19-Apr-12	26-Jun-12 08-Mar-11
1157	CROSSROADS SERVICES INC	Warning Letter	24-Jan-12	20-Aug-10

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
3322	CT Partnership d/b/a Living Water Irrigation	Warning Letter	23-Oct-12	21-Jun-12
1717	C-TECH CORPORATION	Warning Letter	26-Jun-12	17-Jan-11
3872	CULTURED GARDENS	Warning Letter	26-Mar-13	26-Sep-12
3074	CULY CONSTRUCTION & EXCAVATING, INC.	Warning Letter	28-Aug-12	30-May-12
3333			23-Oct-12	04-Jun-12
4267	Culy Contracting, Inc. CUSTOM CONCRETE	Training 1st Level		05-Dec-12
		Training 1st Level	21-May-13	
3841	CUSTOM CONCRETE	Training 1st Level	26-Feb-13	19-Sep-12
3352	CUSTOM CONCRETE	Training 1st Level	23-Oct-12	12-Jul-12
818	CUSTOM CONCRETE	Warning Letter	27-Mar-12	05-Jan-10
363	CUSTOM FENCE COMPANY	Warning Letter	28-Feb-12	03-May-11
353	CUSTOM FENCING	Warning Letter	27-Mar-12	26-Apr-11
4435	Custom Signs Unlimited	Warning Letter	23-Apr-13	28-Jan-13
3419	CUSTOM SIGNS UNLIMITED	Warning Letter	27-Nov-12	26-Jul-12
3477	Cy Stump	Warning Letter	24-Jan-13	09-Jul-12
996	CYPHER LOGIC	Warning Letter	27-Mar-12	09-Jun-10
3792	D AND T DRAIN CLEANING	Warning Letter	26-Mar-13	08-Sep-12
3544	D. R. WATSON COMPANY	Training 1st Level	23-Apr-13	08-Aug-12
3519	D. R. WATSON COMPANY	Warning Letter	26-Feb-13	31-Jul-12
3833	D. R. WATSON COMPANY	Training 1st Level	26-Feb-13	18-Sep-12
4118	D. R. WATSON COMPANY	Training 1st Level	26-Feb-13	14-Nov-12
723	D. R. WATSON COMPANY	Warning Letter	26-Jun-12	13-Oct-09
879	D. R. WATSON COMPANY	Warning Letter	26-Jun-12	26-Mar-10
3431	DALE BREWER	Warning Letter	26-Feb-13	21-Jul-12
3297	Dale Miller	Warning Letter	25-Sep-12	30-Jun-12
4377	Damen Tsouklis	Warning Letter	23-Apr-13	16-Nov-12
1810	DAN CRISTIANI EXCAVATING	Warning Letter	26-Jun-12	28-Mar-11
1603	Dan Dickman	Warning Letter	28-Feb-12	08-May-10
3794	DANIEL GEBO	Warning Letter	26-Mar-13	09-Sep-12
1237	DANUEL KENNETT	Warning Letter	19-Apr-12	14-Sep-10
462	DAVE MURPHY LANDSCAPE	Warning Letter	30-May-12	07-Jun-11
4116	DAVE OMARA CONTRACTOR	Training 2nd Level	23-Apr-13	13-Nov-12
3849	Dave O'Mara Contractor, Inc.	Training 2nd Level	23-Apr-13	20-Sep-12
3889	Dave O'Mara Contractor, Inc.	Training 1st Level	23-Apr-13	28-Sep-12
3850	Dave O'Mara Contractor, Inc.	Training 1st Level	26-Mar-13	20-Sep-12
3629	Dave O'Mara Contractor, Inc.	Training 1st Level	26-Feb-13	22-Aug-12
3411	Dave O'Mara Contractor, Inc.	Training 2nd Level	27-Nov-12	26-Jul-12
2971	Dave O'Mara Contractor, Inc.	Training 1st Level	28-Aug-12	21-May-12
3111	Dave O'Mara Contractor, Inc.	Training 1st Level	28-Aug-12	29-May-12
	Dave O'Mara Contractor, Inc.	Warning Letter	27-Mar-12	29-Jun-11
3344	DAVE'S EXCAVATING	Warning Letter	23-Oct-12	10-Jul-12
	DAVID GREENBERG	Warning Letter	19-Apr-12	13-Aug-11
3724	DAVID HILDENBRAND			
		Warning Letter	24-Jan-13	29-Aug-12
	DAVID SCHACKOW	Warning Letter		04-Aug-12
	David Schwoeppe	Warning Letter		11-Jul-12
	Davis & Sons Excavating	Warning Letter		04-Jan-13
.133	de Boer Egolf Corp	Warning Letter	30-May-12	11-Aug-10

Case	Excavator Name	Penalty	Committee	. Date of
No.	LACOVICO Name	Charles	Date	Damage
2425	de Boer Egolf Corp	Training 1st Level	30-May-12	23-Nov-11
4393	Dean Stump	Warning Letter	23-Apr-13	28-Nov-12
686	DEBRA DAVIDSON	Warning Letter	27-Oct-11	13-Sep-09
4125	DEICHMAN EXCAVATING	Training 1st Level	23-Apr-13	15-Nov-12
1626	DEICHMAN EXCAVATING	Warning Letter	19-Apr-12	22-Nov-10
3230	Denny Hanback	Warning Letter	25-Sep-12	10-Jun-12
3657	Design One Concrete	Warning Letter	27-Nov-12	30-May-12
3090	Diehm Construction Company Inc	Warning Letter	25-Sep-12	07-May-12
3157	DIG EXCAVATING	Warning Letter	23-Oct-12	07-Jun-12
3635	DJ McQuestion Construction Company	Warning Letter	27-Nov-12	07-Jun-12
3282	DONALD SUMMAR	Warning Letter	23-Oct-12	26-Jun-12
3646	Dons Lawn Service and Landscaping Inc	Warning Letter	26-Feb-13	21-Jun-12
3965	Dozer Works LLC	Warning Letter	26-Mar-13	21-Sep-12
3405	E B S IRRIGATION	Warning Letter	27-Nov-12	25-Jul-12
3991	EARTH LINK GEOTHERMAL	Warning Letter	23-Apr-13	03-Oct-12
3174	EAST SIDE VINYL	Warning Letter	28-Aug-12	12-Jun-12
381	ED FILLEY	Warning Letter	30-May-12	09-May-11
3540	ED GAFF & SON	Warning Letter	27-Nov-12	06-Aug-12
481	ED GRABER	Warning Letter	28-Feb-12	14-Jun-11
2945	ED MCGOWAN	Warning Letter	25-Sep-12	10-May-12
3530	ED PATTON CONSTRUCTION INCORPORATED	Warning Letter	26-Feb-13	02-Aug-12
1073	EDWARD LOPEZ	Warning Letter	19-Apr-12	22-Jul-10
4026	EICHER EXCAVATING INCORPORATED	Warning Letter	23-Apr-13	12-Oct-12
1341	ElectriCom, Inc.	Warning Letter	27-Mar-12	06-Oct-10
3990	ELKHART COUNTY HIGHWAY DEPARTMENT	Warning Letter	23-Apr-13	03-Oct-12
4391	Elkhart County Highway Department	Training 1st Level	23-Apr-13	26-Nov-12
3160	ELKHART PUBLIC UTILITIES	Warning Letter	23-Oct-12	11-Jun-12
3087	Ellis Tents & Events - Attn: Keith Griewe	Warning Letter	25-Sep-12	11-Jun-12
815	ELY CONCRETE	Warning Letter	28-Feb-12	30-Dec-09
3932	Emcor Hyre Electric Company of Indiana, Inc.	Warning Letter	26-Mar-13	22-Aug-12
2952	Eric Toth	Warning Letter	25-Sep-12	12-May-12
3963	Erik Foust	Warning Letter	26-Mar-13	11-Sep-12
3496	Estates at Eagles Point LLC	Warning Letter	24-Jan-13	31-Jul-12
3936	Everdry Waterproofing	Warning Letter	26-Mar-13	
4029	F F C FENCING COMPANY	Warning Letter	23-Apr-13	24-Aug-12 15-Oct-12
2964	FAIRFIELD CONTRACTORS INC	Warning Letter	28-Aug-12	
3227				16-May-12
	Farmers Fencing	Warning Letter	25-Sep-12	29-May-12
3068	FE HARDING ASPHALT CO	Warning Letter	28-Aug-12	25-Jun-12
3462	Feikema Sanitation	Warning Letter	24-Jan-13	17-Jul-12
4399	Ferguson Michigan Inc.	Training 1st Level	23-Apr-13	02-Nov-12
4431	Ferguson Michiana Inc.	Warning Letter	23-Apr-13	07-Jan-13
3735	Fiekeme Sanitation	Training 1st Level	26-Feb-13	30-Jul-12
3806	FILSON EARTH WORK COMPANY INCORPORATED	Warning Letter	26-Mar-13	12-Sep-12
1020	FISHER LAND SURVEYING SERVICES, INC.	Warning Letter	28-Feb-12	17-Jun-10
638	Fleck's Trenching & Backhoe Inc.	Warning Letter	19-Apr-12	16-Sep-09

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
1522	Fleenor & Fleenor Excavating	Warning Letter	13-Dec-11	10-Aug-09
66	Fleetwood Excavating	Warning Letter	28-Feb-12	21-Sep-10
4301	FORT WAYNE CITY UTILITIES	Training 1st Level	21-May-13	19-Dec-12
607	FORT WAYNE FENCE LLC	Warning Letter	27-Oct-11	23-Jul-09
3692	Fox Contractor	Training 1st Level	24-Jan-13	30-Aug-12
528	FOX CONTRACTORS	Warning Letter	26-Jun-12	28-Jun-11
2921	FRANK CIGAN	Warning Letter	28-Aug-12	06-May-12
1733	FRONTIER COMMUNICATIONS	Warning Letter	30-May-12	31-Jan-11
377	FRONTIER COMMUNICATIONS	Warning Letter	27-Mar-12	09-May-11
1544	Gaither Bishop	Warning Letter	13-Dec-11	29-Sep-09
4370	Garcia Concrete Const.	Warning Letter	23-Apr-13	31-Oct-12
3349	Gariup Construction Company, Inc.	Training 1st Level	24-Jan-13	11-Jul-12
3276	Gariup Construction Company, Inc.	Training 1st Level	23-Oct-12	26-Jun-12
18	Gariup Construction Company, Inc.	Warning Letter	24-Jan-12	10-Sep-09
1539	Gary Bodenstadt		19-Apr-12	
771	GARY CLARK	Warning Letter	<u> </u>	17-Sep-09 09-Nov-09
2072		Warning Letter	19-Apr-12	· · · · · · · · · · · · · · · · · · ·
	Gary Frye	Warning Letter	19-Apr-12	22-Aug-11
1374	GARY MATERIAL SUPPLY	Warning Letter	24-Jan-12	23-Oct-10
4142	Gatlin Plumbing	Training 1st Level	23-Apr-13	27-Sep-12
3670	Gatlin Plumbing	Training 1st Level	26-Feb-13	06-Aug-12
3415	GATLIN PLUMBING	Training 1st Level	27-Nov-12	26-Jul-12
3093	Gatlin Plumbing	Warning Letter	25-Sep-12	11-May-12
3867	GAYLORD AND SONS	Warning Letter	24-Jan-13	25-Sep-12
3002	GE MARSHALL, INC.	Warning Letter	26-Mar-13	24-May-12
3327	Gehring's Curb Appeal Inc	Warning Letter	23-Oct-12	14-Jun-12
4407	Geiger Excavating	Training 1st Level	21-May-13	30-Dec-12
4526	Geiger Excavating	Training 1st Level	21-May-13	05-Feb-13
4405	Geiger Excavating	Warning Letter	23-Apr-13	28-Dec-12
4434	Geiger Excavating	Training 1st Level	23-Apr-13	02-Jan-13
3421	GENE BALENSIEFER BUILDERS	Warning Letter	27-Nov-12	26-Jul-12
3811	GLIDDEN FENCE	Training 1st Level	26-Feb-13	12-Sep-12
1297	GLIDDEN FENCE	Warning Letter	27-Mar-12	26-Oct-10
3336	Gohman Asphalt & Construction Inc.	Warning Letter	23-Oct-12	02-May-12
3454	Gohmann Asphalt & Construction Inc.	Training 1st Level	24-Jan-13	16-Jul-12
3525	Goodman Construction, Inc.	Warning Letter	26-Feb-13	31-Jul-12
3937	Gordon Engineering	Warning Letter	26-Mar-13	28-Aug-12
3222	Grahams Trucking And Excavating	Warning Letter	25-Sep-12	29-May-12
526	GREEN LANDSCAPING	Warning Letter	28-Feb-12	28-Jun-11
3412	GREENBUD LANDSCAPING	Warning Letter	27-Nov-12	26-Jul-12
1533	Greg Cantrell	Warning Letter	13-Dec-11	08-Sep-09
3226	Gregory Fries	Warning Letter	25-Sep-12	14-May-12
4473	GRIMMER CONSTRUCTION COMPANY	Training 1st Level	21-May-13	14-Feb-13
3643	GRIMMER CONSTRUCTION COMPANY	Warning Letter	24-Jan-13	06-Aug-12
1532	Guthrie Development Group	Warning Letter	30-May-12	03-Sep-09
	HAPPY VALLEY SAND AND GRAVEL	Warning Letter	27-Nov-12	28-Jul-12
3253	Harold Lockart	Warning Letter	23-Oct-12	13-Jun-12

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
3527	HARVEY CONSTRUCTION	Warning Letter	27-Nov-12	02-Aug-12
3698	HARVEY CONSTRUCTION	Training 1st Level	27-Nov-12	31-Aug-12
3520	HAWK ENTERPRISES	Training 1st Level	26-Feb-13	31-Jul-12
3702	HAWK ENTERPRISES	Warning Letter	24-Jan-13	04-Sep-12
3070	HAYES BACKHOE SERVICE	Warning Letter	25-Sep-12	10-May-12
3904	Henry Saylor	Warning Letter	23-Apr-13	26-Aug-12
3470	Herbert Hildebrand	Warning Letter	24-Jan-13	12-Jul-12
2981	HILL T EXCAVATING	Warning Letter	28-Aug-12	22-May-12
2993	HILL T EXCAVATING	Training 1st Level	28-Aug-12	23-May-12
2995	HILL T EXCAVATING	Training 1st Level	28-Aug-12	23-May-12
4412	Hillside Rentals	Warning Letter	21-May-13	17-Dec-12
3694	HIPSKIND CONCRETE	Training 1st Level	26-Mar-13	30-Aug-12
3414	HIPSKIND CONCRETE	Training 1st Level	26-Feb-13	26-Jul-12
1111	HIPSKIND CONCRETE	Warning Letter	19-Apr-12	06-Aug-10
3048	HITTLE LANDSCAPING	Warning Letter	23-Oct-12	05-May-12
490	HOLLAND ENGINEERING	Warning Letter	28-Feb-12	16-Jun-11
4062	HOLMES BROTHERS SEPTIC	Warning Letter	23-Apr-13	25-Oct-12
3422	HOOSIER FOUNDATION	Warning Letter	24-Jan-13	26-Jul-12
3162	HOWELL CONTRACTORS INCORPORATED	Training 1st Level	23-Oct-12	08-Jun-12
3063	HOWELL CONTRACTORS INCORPORATED	Warning Letter	25-Sep-12	08-Jun-12
3118	HOWELL CONTRACTORS INCORPORATED	Training 1st Level	25-Sep-12	31-May-12
3122	HOWELL CONTRACTORS INCORPORATED	Training 1st Level	25-Sep-12	30-May-12
3359	HRP CONSTRUCTION	Training 1st Level	26-Feb-13	12-Jul-12
3503	HRP Construction	Training 1st Level	26-Feb-13	06-Jul-12
3240	HRP Construction	Warning Letter	23-Oct-12	04-May-12
1520	Huber Excavating, Inc	Warning Letter	13-Dec-11	06-Aug-09
3052	HULLAN HALL	Warning Letter	25-Sep-12	11-May-12
3900	Illiana Remedial Action Inc.	Warning Letter	23-Apr-13	31-Jul-12
3533	INDIANA UNDERGROUND CONSTRUCTION	Warning Letter	27-Nov-12	01-Aug-12
4151	INDOT	Warning Letter	26-Mar-13	12-Sep-12
4520	Infrasource Underground Construction	Training 1st Level	21-May-13	31-Jan-13
4329	INFRASOURCE UNDERGROUND CONSTRUCTION	Warning Letter	21-May-13	15-Jan-13
1497	Infrastructure Systems, Inc	Warning Letter	27-Mar-12	12-Aug-10
3554	INNOVATIVE IRRIGATION	Warning Letter	26-Feb-13	04-Aug-12
1970	IRONCLAD EXCAVATING	Warning Letter	26-Jun-12	12-Aug-11
4484	J AND B BUILDERS & Contracting Services, Inc	Warning Letter	21-May-13	25-Feb-13
4067	J B I CONSTRUCTION	Warning Letter	21-May-13	29-Oct-12
4417	J. Jay Graber	Warning Letter	23-Apr-13	19-Dec-12
3235	J. W. Bowles Well Drilling	Warning Letter	25-Sep-12	08-Jun-12
3281	J.D.H. CONTRACTING	Warning Letter	28-Aug-12	26-Jun-12
3985	JACK JACOBS	Warning Letter	23-Apr-13	02-Oct-12
3494	James Eaton	Warning Letter	24-Jan-13	31-Jul-12
2243	JAMES H DREW INCORPORATED	Warning Letter	26-Jun-12	11-Aug-11
1353	JAMES HARRELL	Warning Letter	19-Apr-12	11-Oct-10
3392	JAMES LENGACHER	Warning Letter	27-Nov-12	21-Jul-12
3969	James M Todd	Warning Letter	26-Mar-13	04-Sep-12

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
77	James Spencer	Warning Letter	24-Jan-12	08-Apr-11
3246	James Swoveland	Warning Letter	25-Sep-12	13-Jun-12
74	James Vickers	Warning Letter	24-Jan-12	23-Mar-11
1146	JAMIE GOMEZTAGLE	Warning Letter	30-May-12	17-Aug-10
1515	Jason Kichler	Warning Letter	27-Oct-11	26-Jul-09
3604	JASON STURGEON SUPERIOR SERVICES	Warning Letter	24-Jan-13	21-Aug-12
361	Jay Troy's Sewer & Septic Tank Service	Warning Letter .	28-Feb-12	03-May-11
2994	JEFF MARTIN	Warning Letter	28-Aug-12	23-May-12
4045	JEFF SCHULTZ	Warning Letter	23-Apr-13	19-Oct-12
2986	JENNIFER DIXON	Warning Letter	28-Aug-12	22-May-12
69	Jeremy McCracken	Warning Letter	27-Mar-12	05-Oct-10
1559	Jeremy McCracken	Warning Letter	27-Mar-12	15-Dec-09
1566	Jeremy McCracken	Warning Letter	27-Mar-12	16-Jun-10
3471	Jerry Durflinger	Warning Letter	24-Jan-13	06-Jun-12
4379	Jim Brown	Warning Letter	23-Apr-13	16-Nov-12
3719	JIM DAMMANN	Warning Letter	26-Feb-13	10-Aug-12
1871	JIM GRIFFY	Warning Letter	30-May-12	16-Jul-11
4381	Jim Mills	Warning Letter	23-Apr-13	16-Nov-12
3730	Jim Oswalt	Warning Letter	26-Feb-13	06-Aug-12
898	JJAMCO CONSTRUCTION INC	Warning Letter	24-Jan-12	10-Apr-10
3060	JNL WELL DRILLING SERVICE	Warning Letter	25-Sep-12	30-May-12
1557	Joe Graber Jr Construction	Warning Letter	28-Feb-12	28-Nov-09
54	Joe Luhring	Warning Letter	28-Feb-12	22-Mar-11
3722	Joel Riffel Contracting	Warning Letter	26-Feb-13	12-Sep-12
1804	Johannigman Excavating Inc.	Warning Letter		31-Mar-11
3557	John Boettcher Sewer & Excavating	Warning Letter		09-Aug-12
3935	John Camden Construction	Warning Letter		13-Aug-12
4119	JOHN FERGUSON	Warning Letter		14-Nov-12
3499	John Finlay Jr	Warning Letter		22-Jun-12
2277	JOHN HALL CONSTRUCTION INC	Warning Letter	26-Jun-12	11-Oct-11
976	JOHN HUBER	Warning Letter	19-Apr-12	26-May-10
4385	John Motz	Warning Letter		20-Nov-12
3338	John Mroczek	Warning Letter		14-Jul-12
1230	JOHN O SHAUGHNESSY	Warning Letter	19-Apr-12	11-Sep-10
3747	John Simatovich Homeowner	Warning Letter	26-Feb-13	12-Aug-12
2978		Warning Letter		21-May-12
4134				27-Sep-12
3595		Warning Letter		18-Aug-12
32				11-Oct-10
3501				06-Jul-12
3659			24-Jan-13	09-Aug-12
4148				19-Sep-12
1079				26-Jul-10
3952			······	18-Oct-12
2248				01-Sep-11
1521				07-Aug-09

Case No.	Excavator Name	Penalty	Committee Date	Date of
3465	Ken Woelk	Warning Letter	24-Jan-13	Damage 05-Jul-12
53	Kenneth L Pershon	Warning Letter	27-Mar-12	21-Mar-11
3220		Training 1st Level	23-Oct-12	25-Jun-12
	Kerstiens Homes & Design			
3:4	Kerstiens Homes & Design	Warning Letter	28-Feb-12	18-Oct-10
2948	KEVIN SHARICK UNDERGROUND	Warning Letter	25-Sep-12	11-May-12
3457	Key Concrete, Inc.	Warning Letter	24-Jan-13	12-Jun-12
<u> </u>	K-FEX, Inc.	Warning Letter	27-Oct-11	08-Jul-09
3731	Kimberly Kemper	Warning Letter	26-Feb-13	09-Aug-12
764	KNELLER EXCAVATING	Warning Letter	24-Jan-12	05-Nov-09
3353	KRAEMER CONSTRUCTION	Warning Letter	25-Sep-12	12-Jul-12
3410	KREAGER BROTHERS EXCAVATING, INC.	Warning Letter	24-Jan-13	25-Jul-12
1364	Krooswyk Trucking and Excavating Inc	Warning Letter	21-May-13	26-Sep-12
3798	KRZYSZTOS BOGUCKI	Warning Letter	26-Mar-13	10-Sep-12
L716	LAN-CON ELECTRICAL	Warning Letter	28-Feb-12	14-Jan-11
135	Land Construction Corporation	Training 1st Level	23-Apr-13	26-Sep-12
1414	Land Construction Corporation	Training 1st Level	23-Apr-13	05-Dec-12
666	Land Construction Corporation	Warning Letter	26-Feb-13	25-Jul-12
3741	Lansing Heating and Air Conditioning	Warning Letter	26-Feb-13	06-Aug-12
.258	LARRY HOFFMAN	Warning Letter	19-Apr-12	20-Sep-10
171	LAWRENCE BUILDING CORPORATION	Warning Letter	23-Apr-13	19-Oct-12
491	Lawrence Romano	Warning Letter	24-Jan-13	14-Jul-12
627	LAYNE INLINER	Warning Letter	27-Nov-12	24-Jul-12
-005	LEE HOME RENOVATIONS	Warning Letter	23-Apr-13	08-Oct-12
415	Leepers Lawn Service	Warning Letter	23-Apr-13	12-Dec-12
.892	LEININGER EXCAVATING	Warning Letter	24-Jan-12	21-Jul-11
216	Lica Construction	Warning Letter	25-Sep-12	08-Jun-12
560	LINEAL CONTRACTING	Training 1st Level	26-Feb-13	10-Aug-12
524	LINEAL CONTRACTING	Training 1st Level	27-Nov-12	30-Jul-12
3298	LINEAL CONTRACTING	Training 1st Level	23-Oct-12	04-Jul-12
152	LINEAL CONTRACTING	Warning Letter	28-Aug-12	07-Jun-12
.252	LINEAL CONTRACTING	Warning Letter	27-Mar-12	17-Sep-10
191	LI Enterprises	Warning Letter	23-Apr-13	06-Oct-12
.929	LONE STAR CONCRETE	Warning Letter	28-Aug-12	07-May-12
922	Louthain M R & Assoc.	Warning Letter	26-Mar-13	23-Aug-12
372 372		Training 1st Level	27-Nov-12	
	LUNAR EXCAVATING	<u> </u>		16-Jul-12
425	LUNAR EXCAVATING	Warning Letter	27-Nov-12	29-Jun-12
069	LYNN JACKSON	Warning Letter	23-Oct-12	06-May-12
115	M & K Concrete c/o John Kelly	Warning Letter	25-Sep-12	29-May-12
128	M AND C TRENCHING	Warning Letter	21-May-13	04-Jun-12
	M B CONTRACT TELEPHONE COMPANY			
170	INCORPORATED	Warning Letter	25-Sep-12	11-Jun-12
509	M C Wheeler & Sons Inc	Warning Letter	24-Jan-13	31-Jul-12
233	M Line Electric	Warning Letter	28-Aug-12	22-May-12
113	MAHURIN BORE PRO, INC.	Warning Letter	25-Sep-12	29-May-12
475	Maria Sanchez	Warning Letter	24-Jan-13	04-Jul-12
369	MARK MCCOMB	Warning Letter	27-Nov-12	14-Jul-12

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
3837	MARK MILO ENTERPRISES INC	Warning Letter	26-Mar-13	18-Sep-12
3242	Mark Przybylski	Warning Letter	25-Sep-12	04-Jun-12
4250	MARK TEMPLE TREE SERVICE	Warning Letter	21-May-13	28-Nov-12
4404	Martis Construction	Warning Letter	23-Apr-13	03-Nov-12
3580	MASON ENGINEERING AND CONSTRUCTION	Warning Letter	26-Feb-13	13-Aug-12
3971	Master Built Construction	Warning Letter	26-Mar-13	07-Sep-12
3272	MASTERSCAPE	Warning Letter	25-Sep-12	25-Jun-12
1379	MATT NICCUM EXCAVATING	Warning Letter	19-Apr-12	03-Nov-10
2135				17-Sep-11
	MATTURE CONTRACTING	Warning Letter	30-May-12	<u> </u>
2925	MATTHEW JOHNSON	Warning Letter	28-Aug-12	04-May-12
492	MAXWELL CONSTRUCTION	Warning Letter	28-Feb-12	17-Jun-11
3817	MCALLISTER GENERAL CONTRACTORS	Training 1st Level	26-Mar-13	13-Sep-12
3844	MCALLISTER GENERAL CONTRACTORS	Training 1st Level	26-Mar-13	19-Sep-12
3390	MCALLISTER GENERAL CONTRACTORS	Warning Letter	27-Nov-12	19-Jul-12
3285	MCDOUGALLE CONTRACTING	Warning Letter	23-Oct-12	27-Jun-12
1578	MCF Construction	Warning Letter	28-Feb-12	17-Aug-10
3374	MCKIBBIN EXCAVATING	Warning Letter	26-Feb-13	16-Jul-12
3631	MEHLING CONSTRUCTION	Warning Letter	26-Feb-13	20-Aug-12
1540	Mehringer Plumbing	Warning Letter	24-Jan-12	18-Sep-09
3472	Meredith Excavating	Warning Letter	26-Feb-13	16-Jun-12
3623	MERRYMAN EXCAVATION	Warning Letter	26-Feb-13	01-Aug-12
1577	Michael D Cahill	Warning Letter	28-Feb-12	16-Aug-10
3653	Michael Hendricks Homeowner	Warning Letter	24-Jan-13	08-Aug-12
1396	MICHAEL HINEN	Warning Letter	30-May-12	10-Nov-10
1772	MICHAEL HOCHSTETLER	Warning Letter	30-May-12	08-Mar-11
1366	MICHAEL MCCROREY	Warning Letter	30-May-12	16-Oct-10
4422	Michael McGuire	Warning Letter	23-Apr-13	15-Dec-12
4130	MICHIANA CONTRACTING COMPANY	Training 1st Level	26-Mar-13	10-Sep-12
3155	MICHIANA CONTRACTING COMPANY	Warning Letter	25-Sep-12	07-Jun-12
510	MID STATES CONCRETE	Warning Letter	27-Oct-11	27-Jul-09
3605	MIDWEST EXCAVATING	Warning Letter	26-Feb-13	21-Aug-12
3303	MIDWESTERN ELECTRIC	Training 1st Level	23-Oct-12	02-Jul-12
100	MIDWESTERN ELECTRIC INCORPORATED	Warning Letter	19-Apr-12	16-May-11
1342	Midwestern Electric Incorporated	Warning Letter	19-Apr-12	07-Oct-10
1569	Mike Campbell	Warning Letter	30-May-12	01-Jul-10
1323	MIKE FEDORNOCK	Warning Letter		02-Oct-10
3427		Warning Letter	· · · · · · · · · · · · · · · · · · ·	09-Jul-12
56		Warning Letter		23-Jul-10
	· · · · · · · · · · · · · · · · · · ·	Warning Letter		14-Nov-12
		Training 1st Level		14-Feb-13
		Warning Letter		07-Jul-09
		Warning Letter		02-Jun-11
		Warning Letter		09-Nov-09
		Warning Letter	-	23-Jun-11
		Training 1st Level		18-Oct-12
		Training 1st Level		25-Feb-13

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
3569	MILLER PIPELINE	Training 1st Level	24-Jan-13	15-Aug-12
1171	MILLER PIPELINE	Warning Letter	26-Jun-12	25-Aug-10
1549	Mitchell & Stark Construction	Warning Letter	27-Mar-12	12-Oct-09
1582	Mitchell & Stark Construction	Warning Letter	27-Mar-12	20-Aug-10
3229	Modesto Tamayo Jr	Warning Letter	25-Sep-12	05-Jun-12
3459	Mutton Rental Center	Warning Letter	24-Jan-13	26-Jun-12
1929	MYSTIC HILLS GOLF COURSE	Warning Letter	30-May-12	01-Aug-11
3636	Nicholas Stevens	Warning Letter	24-Jan-13	30-Jun-12
3561	NIEZGODSKI PLUMBING	Training 1st Level	26-Feb-13	10-Aug-12
409	NIEZGODSKI PLUMBING	Warning Letter	27-Mar-12	17-May-11
4228	NIPSCO	Training 1st Level	21-May-13	19-Nov-12
3617	NIPSCO	Training 1st Level	26-Feb-13	23-Aug-12
3301	NIPSCO - Electric	Training 2nd Level	26-Mar-13	02-Jul-12
3332	NIPSCO - Electric	Training 2nd Level	26-Mar-13	05-Jun-12
3612	NIPSCO - Electric	Training 2nd Level	26-Feb-13	22-Aug-12
4023	NIPSCO - Gas	Training 2nd Level	23-Apr-13	11-Oct-12
3679	NIPSCO - Gas	Training 1st Level	26-Feb-13	29-Aug-12
3194	NIPSCO - Gas	Training 1st Level	25-Sep-12	18-Jun-12
2914	NIPSCO - Gas	Warning Letter	28-Aug-12	03-May-12
4359	NixCo Plumbing	Warning Letter	21-May-13	17-Dec-12
1377	NORCO INDUSTRIES	Warning Letter	28-Feb-12	01-Nov-10
3489	North Easter Group	Warning Letter	26-Feb-13	17-Jul-12
3658	Northern Indiana Mechanical	Warning Letter	23-Oct-12	31-Jul-12
 17	Oles Engineering Corporation	Warning Letter	30-May-12	02-Sep-09
4057	OLTHOFF COMPANY INC	Warning Letter	23-Apr-13	25-Oct-12
3733	Overbeck Excavation	Warning Letter	26-Feb-13	22-Jun-12
3277	P M G LANDSCAPING AND IRRIGATION	Warning Letter	23-Oct-12	26-Jun-12
3331	Pape Builders	Warning Letter	23-Oct-12	07-Jun-12
2956	PARAGON LANDSCAPE	Warning Letter	28-Aug-12	14-May-12
3468	Pats Tree Service	Warning Letter	24-Jan-13	25-Jun-12
3871	PAYLESS SEWER AND SEPTIC	Warning Letter	26-Feb-13	26-Sep-12
4278	PELLEY EXCAVATING	Warning Letter	21-May-13	11-Dec-12
3148	PERKINS CONTRACTING Services	Warning Letter	28-Aug-12	06-Jun-12
4181	Pfeiffer Construction	Warning Letter	23-Apr-13	02-Oct-12
3974	PFISTER SPRINKLER SYSTEMS	Warning Letter	23-Apr-13	29-Sep-12
4227	PGX INC	Training 1st Level	23-Apr-13	19-Nov-12
457	PGX INC	Warning Letter	19-Apr-12	06-Jun-11
329	Phil Mellady	Warning Letter	30-May-12	14-Apr-11
1528	Pin Point Directional Drilling	Warning Letter	21-May-13	21-Feb-13
1174	PINPOINT DIRECTIONAL DRILLING, INC	Warning Letter	27-Mar-12	25-Aug-10
3365	PIONEER ASSOCIATES INCORPORATED	Warning Letter	24-Jan-13	13-Jul-12
3650	Plant Center	Warning Letter	24-Jan-13	02-Aug-12
18	Pleasure Pools	Warning Letter	28-Feb-12	17-Feb-11
1158	POINDEXTER EXCAVATING	Warning Letter	27-Mar-12	20-Aug-10
1367	Porch Construction	Warning Letter	23-Apr-13	10-Oct-12
3613	PORTER COUNTY HIGHWAY DEPARTMENT	Warning Letter	26-Feb-13	23-Aug-12

Case No	Excavator Name	Penalty	Committee Date	Date of Damage
3315	POWERS WELDING	Warning Letter	28-Aug-12	05-Jul-12
3231	Precision Utilities Group Inc	Training 1st Level	23-Oct-12	30-May-12
932	PRECISION UTILITIES GROUP INC	Warning Letter	27-Mar-12	29-Apr-10
3054	PRIFOGLE Construction	Warning Letter	28-Aug-12	15-May-12
1654	PRO LAWN CARE AND LANDSCAPING	Warning Letter	28-Feb-12	02-Dec-10
4064	PROFESSIONAL FENCE INC	Warning Letter	26-Feb-13	26-Oct-12
4279	QC COMMUNICATIONS, INC.	Training 1st Level	21-May-13	11-Dec-12
3584	QC COMMUNICATIONS, INC.	Training 1st Level	24-Jan-13	14-Aug-12
3795	QC COMMUNICATIONS, INC.	Training 1st Level	24-Jan-13	10-Sep-12
3836	QC COMMUNICATIONS, INC.	Training 1st Level	24-Jan-13	18-Sep-12
3133	QC COMMUNICATIONS, INC.	Warning Letter	25-Sep-12	01-Jun-12
29	Quinton Stark	Warning Letter	28-Feb-12	10-Oct-10
3576	R AND C FENCE COMPANY	Training 1st Level	26-Feb-13	16-Aug-12
3284	R AND C FENCE COMPANY	Warning Letter	25-Sep-12	27-Jun-12
3062	R L Johnson LLC	Warning Letter	28-Aug-12	07-Jun-12
765	R X EXCAVATING	Warning Letter	19-Apr-12	06-Nov-09
1251	RABER PATIO ENCLOSURES, LLC	Warning Letter	28-Feb-12	17-Sep-10
1530	Ranard's Hauling & Removal	Warning Letter	13-Dec-11	29-Aug-09
3098	Randy Wolf	Warning Letter	25-Sep-12	30-May-12
3469	Ray Lincoln	Warning Letter	24-Jan-13	05-Jul-12
2927	RAYMOND CHAPPELL	Warning Letter	28-Aug-12	05-May-12
534	RELIABLE EXCAVATION	Warning Letter	28-Feb-12	30-Jun-11
3443	REYNOLDS, INC.	Warning Letter	24-Jan-13	05-Jul-12
3444	Reynolds, Inc.	Training 1st Level	24-Jan-13	17-Jul-12
3445	Reynolds, Inc.	Training 1st Level	24-Jan-13	23-Jul-12
3485	Ricardo Montana	Warning Letter	24-Jan-13	29-Jul-12
3143	RICCIS LANDSCAPE MANAGEMENT	Warning Letter	23-Oct-12	06-Jun-12
3083	Rice Contracting	Warning Letter	25-Sep-12	21-May-12
3085	Rice Contracting	Training 1st Level	25-Sep-12	21-May-12
3061	RICHARD E CONTOS	Warning Letter	23-Oct-12	02-Jun-12
3476	Richard Fletcher	Warning Letter	24-Jan-13	21-Jun-12
3480	Richard Johnson	Warning Letter	24-Jan-13	12-May-12
3340	RICHARD SCHULTZ	Warning Letter		09-Jul-12
38	Richard Sparks	Warning Letter		03-Nov-10
2958	RICK KIRKLAND	Warning Letter		14-May-12
4080	RIETH RILEY CONSTRUCTION	Training 2nd Level		31-Oct-12
4362	Rieth Riley Construction Company	Training 2nd Level		23-Aug-12
4127	Rieth Riley Construction Company	Training 2nd Level		29-Aug-12
3514	RIETH-RILEY	Training 2nd Level		27-Jul-12
3669	RIETH-RILEY	Training 1st Level		15-Jun-12
3065	RIETH-RILEY	Warning Letter		12-Jun-12
3267	RIETH-RILEY	Training 1st Level		27-Jun-12
3450	Rivertown Construction LLC	Warning Letter		07-Aug-12
3559	Robert & CHRISTINE JENNESS	Warning Letter Warning Letter		11-Aug-12
3859	ROBERT HENRY CORPORATION	Warning Letter Warning Letter		21-Sep-12
1153	ROBERT KOCHER	Warning Letter Warning Letter		18-Aug-10

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
3474	Robert Phelps Construction	Warning Letter	26-Feb-13	05-Jul-12
3184	ROGER GREESON	Warning Letter	23-Oct-12	13-Jun-12
45	Roger Mills	Warning Letter	24-Jan-12	25-Jan-11
859	RON JONES	Warning Letter	30-May-12	09-Mar-10
1556	Ron Story	Warning Letter	24-Jan-12	22-Nov-09
1529	Ronald J. Vanwazer	Warning Letter	27-Oct-11	28-Aug-09
4383	Ronald S. Bunt, Inc	Warning Letter	23-Apr-13	23-Nov-12
3734	ROTHENBERGER COMPANY, INC.	Training 1st Level	26-Feb-13	08-Aug-12
2947	ROTHENBERGER COMPANY, INC.	Warning Letter	25-Sep-12	10-May-12
4105	ROTO ROOTER	Warning Letter	23-Apr-13	08-Nov-12
3956	Rowdys Recycle	Warning Letter	26-Mar-13	12-Sep-12
466	RUFUS H SMITH INC	Warning Letter	30-May-12	07-Jun-11
3752	Ryan Schleman	Warning Letter	26-Mar-13	04-Aug-12
3481	Ryan Vaught	Warning Letter	24-Jan-13	14-Jul-12
3510	S & S Construction	Warning Letter	26-Feb-13	27-Jul-12
3385	S & S Directional Boring	Warning Letter	21-May-13	18-Jul-12
3656	S & S Directional Boring	Warning Letter	24-Jan-13	23-Aug-12
3575	S AND L BUILDERS	Warning Letter	24-Jan-13	16-Aug-12
4087	S AND T BANCROFT ELECTRIC INC	Warning Letter	23-Apr-13	01-Nov-12
4221	S AND T BANCROFT ELECTRIC INC	Training 1st Level	23-Apr-13	16-Nov-12
3894	Sauer Land Surveying	Warning Letter	26-Mar-13	25-Jul-12
3648	Schenkel Construction	Warning Letter	27-Nov-12	02-Jul-12
3066	SCHUTT - LOOKABILL Co., Inc	Warning Letter	25-Sep-12	13-Jun-12
2955	SCOTT PARRISH	Warning Letter	28-Aug-12	14-May-12
3218	SEAN T HARROLD	Warning Letter	23-Oct-12	13-Jun-12
40	Sedam Contracting Corp	Warning Letter	28-Feb-12	12-Nov-10
2016	SEI EXCAVATING	Warning Letter	26-Jun-12	23-Aug-11
3131	SELGE CONSTRUCTION COMPANY, INC.	Training 1st Level	23-Oct-12	05-Jun-12
3209	SELGE CONSTRUCTION COMPANY, INC.	Warning Letter	23-Oct-12	20-Jun-12
3354	SENIOUR CONSTRUCTION	Warning Letter	23-Oct-12	12-Jul-12
3649	Shawnee Construction & Engineering.	Warning Letter	27-Nov-12	18-Jul-12
4154	Sheehy Well & Pump Co	Warning Letter	23-Apr-13	15-Oct-12
3067	SHEILA WATSON	Warning Letter	25-Sep-12	17-Jun-12
3742	Shipshewana Campgrounds	Warning Letter	24-Jan-13	09-Aug-12
1535	Silling & Co, LLC	Warning Letter	13-Dec-11	12-Sep-09
3949	Southern Indiana Drainage Corp., Inc.	Warning Letter	23-Apr-13	04-Oct-12
748	SPECTRA TECH	Warning Letter	28-Feb-12	27-Oct-09
4106	ST JOSEPH COUNTY HIGHWAY DEPTRIVERSIDE	Warning Letter	23-Apr-13	09-Nov-12
3089	Star Builders	Warning Letter	25-Sep-12	25-May-12
577	STEINER TRENCHING	Warning Letter	13-Dec-11	13-Aug-09
3637	Stephen Duff	Warning Letter	24-Jan-13	15-Aug-12
3655	Stephen Springer Homeowner	Warning Letter	24-Jan-13	19-Aug-12
16	Steve Carothers	Warning Letter	27-Mar-12	05-Feb-11
3221	Steves Landscaping Lawn & Garden	Warning Letter	25-Sep-12	18-May-12
3571	STONEMOR GROUP	Warning Letter	24-Jan-13	15-Aug-12
3934	Stromback Brothers Inc	Warning Letter	26-Mar-13	24-Aug-12

Case No.	Excavator Name	Penalty	Committee Date	Date of Damage
4336	SUN COMMUNICATIONS	Training 2nd Level	21-May-13	23-Jan-13
4044	SUN COMMUNICATIONS	Training 1st Level	23-Apr-13	19-Oct-12
3838	SUN COMMUNICATIONS .	Warning Letter	26-Feb-13	18-Sep-12
4122	SUN COMMUNICATIONS	Training 1st Level	26-Feb-13	15-Nov-12
1273	SUNESIS CONSTRUCTION	Warning Letter	27-Mar-12	18-Oct-10
3100	Tad Freed	Warning Letter	28-Aug-12	13-May-12
1729	TATE CONCRETE	Warning Letter	28-Feb-12	27-Jan-11
1561	Temple & Tem ple Excavating	Warning Letter	27-Mar-12	09-Jun-10
1319	TERRY MINIX	Warning Letter	30-May-12	30-Sep-10
3740	The Concrete Guys	Warning Letter	26-Feb-13	28-Jun-12
1063	THOMAS BOYD	Warning Letter	30-May-12	17-Jul-10
3364	THREE MEN CREW INCORPORATED	Warning Letter	27-Nov-12	13-Jul-12
2122	TIM WILCHER	Warning Letter	19-Apr-12	11-Sep-11
3237	Timothy Harvey	Warning Letter	25-Sep-12	12-May-12
4207	Tim's Landscape Services Inc	Warning Letter	23-Apr-13	24-Oct-12
4380	TLM Inc.	Warning Letter	23-Apr-13	02-Nov-12
3318	TOVEY PERRY COMPANY	Warning Letter	28-Aug-12	05-Jul-12
3671	Town & Country Builders	Warning Letter	24-Jan-13	07-Aug-12
4192	Town & Country Fence Inc	Warning Letter	23-Apr-13	09-Oct-12
3633	Town of Brookville	Warning Letter	23-Oct-12	12-Jul-12
3639	Town of Chesterton	Warning Letter	24-Jan-13	13-Aug-12
3256	Town of Fishers	Warning Letter	23-Oct-12	21-Jun-12
	TOWN OF FOWLER MUNICIPAL	Warning Letter	19-Apr-12	23-Aug-10
	Town of Goodland	Warning Letter	21-May-13	30-Jan-13
	TOWN OF HEBRON	Warning Letter		01-Aug-12
	Town of Silver Lake	Warning Letter		10-May-12
3549	Transco Railroad Products		26-Feb-13	06-Aug-12
3813	TRAVIS FORD			12-Sep-12
1563	Traylor Construction			14-Jun-10
	TROY SCOTT		28-Aug-12	04-May-12
		Warning Letter		
				19-Jul-12
			28-Feb-12	02-Aug-10
				 23-Jul-12
				22-Jun-12
581				19-Aug-09
	***************************************			22-May-12
				03-Jun-12
				10-May-12
				, 25-Jun-12
				02-Nov-12
				27-Jun-12
				18-May-12
				17-Aug-12
				20-Sep-12
				08-Aug-12

Case	Excavator Name	Penalty	Committee	Date of
No.	EXCAVATOR NATIVE		Date	Damage
2999	WALSH AND KELLY	Warning Letter	28-Aug-12	24-May-12
3442	Walsh Construction	Warning Letter	27-Nov-12	30-May-12
3550	WALTERS EXCAVATING	Warning Letter	24-Jan-13	06-Aug-12
3381	WATSON'S EXCAVATING	Warning Letter	27-Nov-12	17-Jul-12
37	Watts Brothers	Warning Letter	28-Feb-12	01-Nov-10
3451	Watts Brothers Construction	Training 1st Level	26-Feb-13	26-Jul-12
3449	Watts Brothers Construction	Training 1st Level	24-Jan-13	26-Jul-12
2972	WEBER Concrete	Warning Letter	28-Aug-12	18-May-12
1974	WIGENT EXCAVATING	Warning Letter	19-Apr-12	17-Aug-11
15	William E Settle & Son	Warning Letter	13-Dec-11	14-Aug-09
3750	William McMahon	Warning Letter	24-Jan-13	23-Aug-12
4396	William Molnar	Warning Letter	21-May-13	03-Nov-12
3647	Willie Oxendine Excavating	Warning Letter	27-Nov-12	28-Jun-12
2937	WINGHAM CONCRETE	Warning Letter	25-Sep-12	09-May-12
3367	Wisel Enterprises LLC	Warning Letter	23-Oct-12	13-Jul-12
4138	Wissco Irrigation	Training 1st Level	26-Mar-13	17-Sep-12
3154	WISSCO IRRIGATION	Warning Letter	23-Oct-12	07-Jun-12
3473	Woodruff & Sons, Inc.	Training 1st Level	26-Feb-13	27-Jun-12
3614	Woodruff & Sons, Inc.	Training 1st Level	26-Feb-13	23-Aug-12
3102	Woodruff & Sons, Inc.	Warning Letter	25-Sep-12	18-May-12
4368	Woodruff and Sons	Training 1st Level	21-May-13	17-Oct-12
4143	Woodruff and Sons	Training 1st Level	23-Apr-13	24-Sep-12
26	Yoder Construction	Warning Letter	24-Jan-12	10-May-10
1180	YORK CONSTRUCTION	Warning Letter	30-May-12	26-Aug-10

	1.					
	·					
			,	•		
	*					
					1	
					• •	
		•				
					•	

Operator Penalties

Case	Operator Name	Penalty	Committee	Date of
No.	Operator Name	Penalty	Date	Damage
3130	CITIZENS GAS	Training 1st Level	21-May-13	5-Jun-12
3156	CITIZENS GAS	Training 1st Level	21-May-13	7-Jun-12
3429	Citizens Gas	Training 1st Level	21-May-13	17-Jul-12
3432	Citizens Gas	Training 1st Level	21-May-13	23-Jul-12
3433	Citizens Gas	Training 1st Level	21-May-13	26-Jul-12
3434	Citizens Gas	Training 1st Level	21-May-13	8-Jun-12
3058	Citizens Gas	Training 1st Level	24-Jan-13	24-May-12
3073	Citizens Gas	Training 1st Level	24-Jan-13	24-May-12
3114	CITIZENS GAS	Training 1st Level	24-Jan-13	29-May-12
3053	Citizens Gas	Warning Letter	27-Nov-12	14-May-12
1596	Jasper Municipal Gas	Warning Letter	30-May-12	1-Mar-10
3195	Midwest Natural Gas Corporation	Warning Letter	21-May-13	18-Jun-12
3126	NIPSCO	Training 1st Level	21-May-13	31-May-12
3324	NIPSCO	Training 1st Level	21-May-13	11-Jun-12
3458	NIPSCO	Training 1st Level	21-May-13	13-Jun-12
3461	NIPSCO	Training 1st Level	21-May-13	23-Jun-12
3463	NIPSCO	Training 1st Level	21-May-13	30-Jun-12
3466	NIPSCO	Training 1st Level	21-May-13	9-Jul-12
3479	NIPSCO	Training 1st Level	21-May-13	11-May-12
3487	NIPSCO	Training 1st Level	21-May-13	17-Jul-12
3493	NIPSCO	Training 1st Level	21-May-13	2-Aug-12
3502	NIPSCO	Training 1st Level	21-May-13	10-Jul-12
3504	NIPSCO	Training 1st Level	21-May-13	23-Jul-12
3522	NIPSCO	Training 1st Level	21-May-13	30-Jul-12
3526	NIPSCO	Training 1st Level	21-May-13	31-Jul-12
3528	NIPSCO	Training 1st Level	21-May-13	2-Aug-12
-3531	NIPSCO	Training 1st Level	21-May-13	2-Aug-12
3538	NIPSCO	Training 1st Level	21-May-13	2-Aug-12
3541	NIPSCO	Training 1st Level	21-May-13	7-Aug-12
3545	NIPSCO	Training 1st Level	21-May-13	8-Aug-12
4426	NIPSCO	Training 1st Level	21-May-13	18-Dec-12
4034	NIPSCO	Training 2nd Level	23-Apr-13	16-Oct-12
3210	NIPSCO	Training 1st Level	26-Feb-13	20-Jun-12
3280	NIPSCO	Training 1st Level	26-Feb-13	26-Jun-12
3347	NIPSCO	Training 1st Level	26-Feb-13	10-Jul-12
2992	NIPSCO	Training 1st Level	24-Jan-13	23-May-12
3106	NIPSCO	Training 1st Level	24-Jan-13	25-May-12
3142	NIPSCO	Training 1st Level	24-Jan-13	6-Jun-12
3151	NIPSCO	Training 1st Level	24-Jan-13	6-Jun-12
3159	NIPSCO	Training 1st Level	24-Jan-13	11-Jun-12
3175	NIPSCO	Training 1st Level	24-Jan-13	12-Jun-12
3183	NIPSCO	Training 1st Level	24-Jan-13	13-Jun-12
3192	NIPSCO	Training 1st Level	24-Jan-13	18-Jun-12
3205	NIPSCO	Training 1st Level	24-Jan-13	20-Jun-12
3206	NIPSCO	Training 1st Level	24-Jan-13	20-Jun-12

Operator Penalties

Case No.	Operator Name	Penalty	Committee Date	Date of Damage
3236	NIPSCO	Training 1st Level	24-Jan-13	2-May-12
3289	NIPSCO	Training 1st Level	24-Jan-13	28-Jun-12
3291	NIPSCO	Training 1st Level	24-Jan-13	28-Jun-12
3294	NIPSCO	Training 1st Level	24-Jan-13	29-Jun-12
3296	NIPSCO	Training 1st Level	24-Jan-13	29-Jun-12
3305	NIPSCO	Training 1st Level	24-Jan-13	· 3-Jul-12
3398	NIPSCO	Training 1st Level	24-Jan-13	23-Jul-12
2940	NIPSCO	Training 1st Level	27-Nov-12	9-May-12
2962	NIPSCO	Training 1st Level	27-Nov-12	15-May-12
2970	NIPSCO	Training 1st Level	27-Nov-12	21-May-12
2990	NIPSCO	Training 1st Level	27-Nov-12	23-May-12
2915	NIPSCO	Warning Letter	28-Aug-12	3-May-12
2984	NIPSCO	Training 1st Level	28-Aug-12	22-May-12
60	NIPSCO	Warning Letter	30-May-12	7-Sep-10
371	NIPSCO	Warning Letter	30-May-12	5-May-11
383	NIPSCO	Warning Letter	30-May-12	10-May-11
399	NIPSCO	Warning Letter	30-May-12	16-May-11
806	NIPSCO	Warning Letter	30-May-12	16-Dec-09
3120	Vectren	Training 1st Level	21-May-13	30-May-12
3386	Vectren	Training 1st Level	21-May-13	18-Jul-12
3535	Vectren	Training 1st Level	21-May-13	1-Aug-12
3537	Vectren	Training 1st Level	21-May-13	1-Aug-12
3543	Vectren	Training 1st Level	21-May-13	7-Aug-12
3288	Vectren	Training 1st Level	26-Feb-13	28-Jun-12
3360	Vectren ·	Training 1st Level	26-Feb-13	12-Jul-12
3815	Vectren	Training 1st Level	26-Feb-13	. 13-Sep-12
3001	Vectren	Training 1st Level	24-Jan-13	24-May-12
3107		Training 1st Level	24-Jan-13	25-May-12
3125	Vectren	Training 1st Level	24-Jan-13	31-May-12
3135	Vectren	Training 1st Level	24-Jan-13	5-Jun-12
3138		Training 1st Level	24-Jan-13	4-Jun-12
3146		Training 1st Level	24-Jan-13	6-Jun-12
		Training 1st Level	24-Jan-13	9-Jun-12
		Training 1st Level	24-Jan-13	11-Jun-12
		Training 1st Level	24-Jan-13	19-Jun-12
		Training 1st Level	24-Jan-13	19-Jun-12
		Training 1st Level	24-Jan-13	22-Jun-12
		Training 1st Level	24-Jan-13	26-Jun-12
		Training 1st Level	24-Jan-13	3-Jul-12
		Training 1st Level	24-Jan-13	5-Jul-12
		Training 1st Level	27-Nov-12	7-May-12
		Training 1st Level Training 1st Level	27-Nov-12	10-May-12
		Training 1st Level	27-Nov-12 27-Nov-12	10-May-12 15-May-12
		Training 1st Level	27-Nov-12 27-Nov-12	15-May-12
2503	vecuen	Hallillig TSf FeA61	71-MOA-17	TD-IAIGA-T7

Operator Penalties

Case No.	Operator Namë	Penalty	Committee Date	Date of Damage
2983	Vectren	Training 1st Level	27-Nov-12	22-May-12
3140	Vectren	Warning Letter	23-Oct-12	4-Jun-12
893	Vectren	Warning Letter	30-May-12	6-Apr-10

	. <i>*</i>			
·				
		~		
	·			
	٠.			

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: Vectren Other Party: Telecom Placement, Inc. Case No.: 3120 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation /No Violation Recommended Penalty: Training Additional Information: Slagle abstains APPROVED: Dan Meiners (initialed)

Vice Chairman



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Telecom Placement, Inc.

UPPAC Database Record ID: 3120

Investigator: Mike Orr Report Date: 1/2/2013

Damage Date: 5/30/2012 2:17:07 PM

Damage Address: 8023 N Mount Comfort Rd

City: Mccordsville County: Hancock

The Parties

Excavator: Telecom Placement, Inc.

Contact: Tony Harvey

Address: 15405 Little Eagle Creek Avenue, Zionsville, In 46077

Telephone:

Facility Owner: Vectren

Contact: Darlene Kulhanek

Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Indiana Undergrou	ınd Plant	Protection	Advisory
Committee Recomm	endation to	IURC	
Respondent: Other Party: Case No.: Date of Advisory Meeting:	NIPSCO M and C Tree 3126 May 21, 2013	nching	
Statutes Allegedly Violated IC 8-1-26-18(f)	d:		
Violation No Violation			
Recommended Penalty:			
Additional Information:			
APPROVED: Rick Slagle Chairman			



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: M And C Trenching

UPPAC Database Record ID: 3126

Report Date: 04/17/2013

Investigator: William Boyd

Damage Date: 5/31/2012 1:46:03 PM

Damage Address: 6885 W North Lake Gage Dr, Orland, Steuben County

The Parties

Excavator: M And C Trenching (Contractor)

Address: 4745 East In Rt 120, Fremont, In 46737

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas Facility Function: Service/Drop

Type of Equipment: Directional Drilling

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$740

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1205250136

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator damaged a natural gas service during a boring procedure to install sewer facilities.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 7/17/2012. The damaged service had not been marked prior to the commencement of the boring procedure.

Conclusion: The operator failed to locate and mark the service.

	lerground Pla ecommendatio	nt Protection n to IURC	n Advisory
Respondent: Other Party: Case No.: Date of Advisory I	M and C NIPSCO 3128 Meeting: May 21, 2		
Statutes Allegedly IC 8-1-26-20(a)(2)			
Violation No Vio	lation		
Recommended Per	nalty: (Uarnin	g letter	
Additional Informa	ation:		
,	k Slagle		



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: M And C Trenching

UPPAC Database Record ID: 3128

Report Date: 04/17/2013

Investigator: William Boyd

Damage Date: 6/4/2012 9:04:12 AM

Damage Address: 6885 W North Lake Gage Dr, Orland, Steuben County

The Parties

Excavator: M And C Trenching (Contractor)

Address: 4745 East In Rt 120, Fremont, In 46737

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1205250136

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator struck and damaged a plastic natural gas service during excavation to install sewer facilities.


Findings: Reported by Indiana 811; excavator's response to initial notice was received on 7/17/2012. There was an abandoned line close to the live service; both had been exposed but the backhoe clipped the live service enough to cause damage.

Conclusion: Excavator failed to maintain the required clearance from the gas facility.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Indiana Undergrou Committee Recomm			Advisory
Respondent: Other Party: Case No.: Date of Advisory Meeting:	Citizens Gas Citizens Water 3130 May 21, 2013	r Company	
Statutes Allegedly Violated IC 8-1-26-18(f)	l: ·		
Violation No Violation			
Recommended Penalty:			
Additional Information: Wa	arren abstains		
	:		
APPROVED: Rick Slagle Chairman	······································		





Pipeline Safety Division Investigation Report

Investigation regarding: Citizens Water Company

UPPAC Database Record ID: 3130

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/5/2012 10:20:45 AM

Damage Address: 3507 / Georgetown Rd, Indianapolis, Marion

The Parties

Excavator: Citizens Water Company

Address: 1220 Waterway Boulevard, Indianapolis, In 46202

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1205151718

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 8/13/2012. The operator and the excavator reported the natural gas line was incorrectly marked.

Conclusion: There was a failure to provide accurate locate markings.

Indiana Undergrou Committee Recomm		Advisory
Respondent: Other Party: Case No.: Date of Advisory Meeting:	Citizens Gas Citizens Wate 3156 May 21, 2013	
Statutes Allegedly Violated IC 8-1-26-18(f)	d:	
Violation No Violation		
Recommended Penalty:		
Additional Information: <u>W</u>	arren abstains	
APPROVED: (initialed) Rick Slagle Chairman		



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Citizens Water Company

UPPAC Database Record ID: 3156

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/7/2012 1:45:27 PM

Damage Address: 523 Bernard Ave, Indianapolis, Marion

The Parties

Excavator: Citizens Water Company

Address: 2150 Martin Luther King Jr Street, Indianapolis, In 46202

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 23

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1205252079

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to repair a water line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 8/13/2013. The excavator had a valid locate request. Both the operator and excavator reported the gas line was incorrectly marked.

Conclusion: There was a failure to provide accurate locate markings.

Indiana Undergrou Committee Recomm	and Plant Protection Advisory sendation to IURC		
Respondent: Other Party: Case No.: Date of Advisory Meeting:	Midwest Natural Gas Corporation Dave O'Mara Contractor, Inc. 3195 May 21, 2013		
Statutes Allegedly Violated IC 8-1-26-18(f)	1:		
Violation No Violation			
Recommended Penalty: Naming letter			
Additional Information:			
APPROVED: Rick Slagle Chairman			



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Dave O'mara Contractor, Inc.

UPPAC Database Record ID: 3195

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/18/2012 1:18:20 PM

Damage Address: 129 W Poplar St, North Vernon, Jennings

The Parties

Excavator: Dave O'mara Contractor, Inc.

Address: 1100 East O And M Avenue, North Vernon, In 47265

Facility Owner: Midwest Natural Gas Corporation

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: WATER

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1206060149

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 8/10/2012. The excavator had a valid locate request. The operator reported the gas line had been retired on the opposite side of the street from the main. This left a service stub under the road and no documentation to indicate it existed. The operator has revised the procedures on how they retire facilities.

Conclusion: There was a failure to provide locate markings due to inaccurate maps and records.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **NIPSCO** Other Party: South Whitley Excavating Case No.: 3324 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: Training Additional Information: APPROVED: < Rick Slagle (initialed)

Chairman



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: South Whitley Excavating

UPPAC Database Record ID: 3324

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/11/2012

Damage Address: 4970 E Smith St, Columbia City, Whitley

The Parties

Excavator: South Whitley Excavating

Address: 8744 S 700 East, Piercton, In 46562

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Demolition

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1205291858

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service stub was damaged during excavation for demolition of a building.

Findings: Reported by NIPSCO; excavator failed to respond to initial notice. The excavator had a valid locate request. The operator failed to provide locate marks for the undocumented service stub.

Conclusion: There was a failure to provide locate markings.

Violation: 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.

NOTE: The operator reported the failure to provide locate markings due to the line being undocumented.

	iderground			Advisory
Committee I	Recommenda	ation to	IURC	
Respondent: Other Party: Case No.: Date of Advisor	NIP: 3385	SCO	onal Boring	
Statutes Alleged IC 8-1-26-16(g)	ly Violated:			
Violation No V	iolation			
Recommended F	enalty: 1eHer			
Additional Infor	mation:			
				· · · · · · · · · · · · · · · · · · ·
APPROVED:	ick Slagle			
,	hairman			



http://www.in.gov/iure Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: S & S Directional Boring

UPPAC Database Record ID: 3385

Report Date: 4/18/2013 Investigator: Howard Friend

Damage Date: 7/18/2012 11:29:39 AM Damage Address: S Martin St, Ligonier, Noble

The Parties

Excavator: S & S Directional Boring

Address: 1116 County Road 17, Bryan, Ohio 43506

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas Facility Function: Distribution

Type of Equipment: Directional Drilling Type of Work Performed: Sewer

Damage Impact

Product Release: Yes Ignition: No

Service Interruption: True Number of Customers Affected: 20

Injuries: 0 Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No Indiana 811 Ticket Number: Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A four (4) inch natural gas line was damaged during directional boring operations to install a sewer.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice which was deliverd and signed for on 2/20/2013. This original excavator, Land Construction, provided notice of excavation. They contracted out the directional bore operation to the excavator named in this case and they failed to provide notice of excavation. It is important to know that the operator exposed the gas facility for the excavator prior to the boring operation. The operator informed the excavator not to boring the water near the gas facility.

Conclusion: There was a failure to provide notice of excavation by the boring excavator.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Indiana Underground Plant Protection Advisory Committee Recommendation to IURC
Respondent: Vectren Other Party: Environmental Construction
Case No.: 3386 Date of Advisory Meeting: May 21, 2013
Statutes Allegedly Violated: IC 8-1-26-18(f)
Violation No Violation
Recommended Penalty: (Second)
Additional Information: Slagle abstains
APPROVED: Laniet Meinen
(initialed) Dan Meiners Vice Chairman



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Environmental Construction Incorporated

UPPAC Database Record ID: 3386

Report Date: 4/18/2013 Investigator: Mike Orr

Damage Date: 7/18/2012 1:13:12 PM Damage Address: 351 Nw E St, Richmond, Wayne

The Parties

Excavator: Environmental Construction Incorporated

Address: 13150 West Co Rt 300 North, Yorktown, In 47396

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas Facility Function: Service/Drop

Damage Impact

Product Release: Yes Ignition: No

Service Interruption: True Number of Customers Affected: 1

Injuries: 0 Fatalities: 0 Repair Cost (if known): \$630.42

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes Indiana 811 Ticket Number: 1207090183 Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A 1" steel service was damaged during excavation to repair a water line.

Findings: Reported by Indiana 811; the excavator failed to respond to initial notice. The excavator had a valid locate request. The operator reports the line was not accurately located due to incorrect maps and records.

Conclusion: There was a failure to provide accurate locate markings.

Indiana Underg	round Plant Protection	Advisory
Committee Recor	nmendation to IURC	
Respondent: Other Party: Case No.: Date of Advisory Meet	Citizens Gas Smith Projects, Inc. 3429 ing: May 21, 2013	
Statutes Allegedly Violation No Violation		
Recommended Penalty	Second)	
Additional Information	: Warren abstains	
APPROVED: (initialed) Rick Sla Chairma	_	



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Smith Projects, Inc.

UPPAC Database Record ID: 3429

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 7/17/2012

Damage Address: 6810 S Meridian St, Indianapolis, Marion

The Parties

Excavator: Smith Projects, Inc.

Address: 500 Rangeline Rd, Morristown, In 46161

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Drainage

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207031253

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation to install drainage.

Findings: Reported by Citizens Gas; excavator failed to respond to initial notice. The excavator had a valid locate request however, the operator failed to provide accurate locate markings.

Conclusion: Operator failed to provide accurate locate markings.

Respondent:	Citizens Gas	
Other Party:	Lykins Contracting	
Case No.:	3432	
Date of Advisory Meeting	g: May 21, 2013	
Statutes Allegedly Violate IC 8-1-26-18(f)	ed:	
Violation No Violation		•
Recommended Penalty:	second)	
Additional Information: <u>V</u>	Varren abstains	en e
·		
1		
APPROVED:		
(initialed) Rick Slagle	e	
Chairman		



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Lykins Contracting

UPPAC Database Record ID: 3432

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 7/23/2012

Damage Address: 4934 Manker St, Indianapolis, Marion

The Parties

Excavator: Lykins Contracting

Address: 12783 N St Rd 101, Sunman, In 47041

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207110082

Original Start Date:

Locate Instructions:


Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for road work.

Findings: Reported by Citizens Gas; excavator failed to respond to initial notice. The excavator had a valid locate request however, the operator failed to provide locate markings.

Conclusion: Operator failed to locate or provided incorrect locate markings

	Inderground Recommen		Protection IURC	Advisory
Respondent: Other Party: Case No.: Date of Adviso		33	ntractors, LP	
Statutes Allege IC 8-1-26-18(•			
Violation No	Violation			
Recommended	• /	ond)		
Additional Info	ormation: Warre	n abstains		
		T		
No. of the last of				
APPROVED:				
(initialed) -	Rick Slagle Chairman			·





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Milestone Contractors, LP

UPPAC Database Record ID: 3433

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 7/26/2012

Damage Address: 7072 Emblem Dr, Indianapolis, Marion

The Parties

Excavator: Milestone Contractors, LP

Address: P.o. Box 421459, Indianapolis, In 46242

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207122167

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for road work.

Findings: Reported by Citizens Gas; excavator's response to initial notice was received on 9/28/2012. The excavator had a valid locate request and reported the damaged service was not located prior to excavation. The excavator provided pictures that support their findings that the gas line was not marked.

Conclusion: There was a failure to provide accurate locate markings.

Indiana Underground Plant Protection	Advisory
Committee Recommendation to IURC	
Respondent: Citizens Gas Other Party: Power Environments Case No.: 3434 Date of Advisory Meeting: May 21, 2013	
Statutes Allegedly Violated: IC 8-1-26-18(f)	
Violation No Violation	• • • • • • • • • • • • • • • • • • •
Recommended Penalty:	
Additional Information: Warren abstains	radio frants de la companya del companya del companya de la compan
APPROVED:	
(initialed) Rick Slagle Chairman	



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Power Environments

UPPAC Database Record ID: 3434

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/8/2012

Damage Address: 1659 N New Jersey St, Indianapolis, Marion

The Parties

Excavator: Power Environments

Address: 6130 S Belmont Ave. A, Indianapolis, In 46217

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Hand Tools

Type of Work Performed: Pole

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 8

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to install a pole.

Findings: Reported by Citizens Gas; excavator failed to respond to initial notice. The excavator provided notice of excavation however, the operator reports the facility was not marked.

Conclusion: There was a failure to provide locate markings.

Indiana Underground Plant Protection Advisory
Committee Recommendation to IURC
Respondent: NIPSCO Other Party: Fort Wayne Water Department Case No.: 3458 Date of Advisory Meeting: May 21, 2013
Statutes Allegedly Violated: IC 8-1-26-18(f)
Violation No Violation
Recommended Penalty:
Additional Information:
APPROVED: (initialed) Rick Slagle Chairman



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Fort Wayne Water Department

UPPAC Database Record ID: 3458

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/13/2012

Damage Address: 1210 Dell Cove Dr, Fort Wayne, Allen

The Parties

Excavator: Fort Wayne Water Department

Address: 200 E Berry St, Fort Wayne, In 46802

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$704.45

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1206062275

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a water line.

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 10/15/2012. The excavator had a valid locate request however, the operator failed to provide accurate locate marks.

Conclusion: The operator failed to provide accurate locate marks.

Indiana Undergrou Committee Recomm	and Plant nendation to		Advisory
Respondent: Other Party: Case No.: Date of Advisory Meeting:	NIPSCO Araceli Alanz 3461 May 21, 2013	0	
Statutes Allegedly Violated IC 8-1-26-18(f)	d:		
Violation No Violation			
Recommended Penalty:			
Additional Information:			· · · · · · · · · · · · · · · · · · ·
APPROVED: Rick Slagle	·		·
Chairman			



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Araceli Alanzo

UPPAC Database Record ID: 3461

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/23/2012

Damage Address: 522 S Wayne St, Gary, Lake

The Parties

Excavator: Araceli Alanzo

Address: 522 S Wayne St, Gary, In

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$555.05

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1206152829

Original Start Date:

Locate Instructions:


Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation to repair a water line.

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 10/8/2012. The excavator had a valid locate however, the locate contractor failed to locate the natural gas facility.

Conclusion: There was a failure to locate the natural gas facility.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **NIPSCO** Other Party: **Troy Cripe** Case No.: 3463 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: raining Additional Information: APPROVED: Rick Slagle (initialed)





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Troy Cripe

UPPAC Database Record ID: 3463

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 6/30/2012

Damage Address: 16263 Cr 22, Goshen, Elkhart

The Parties

Excavator: Troy Cripe

Address: 16263 Cr 22, Goshen, In

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Trencher

Type of Work Performed: Irrigation

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$628.17

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1206193507

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for irrigation

Findings: Reported by NIPSCO; excavator failed to respond to initial notice. The excavator had a valid locate request. The operator failed to locate the gas service stub due to inaccurate maps and records.

Conclusion: There was a failure to locate the gas facility.

Indiana Undergrou Committee Recomm	and Plant Protection endation to IURC	Advisory
Respondent: Other Party: Case No.: Date of Advisory Meeting:	NIPSCO City Of Kokomo 3466 May 21, 2013	
Statutes Allegedly Violated IC 8-1-26-18(f)	1:	
Violation No Violation		
Recommended Penalty:	econd)	
Additional Information:		
APPROVED: Rick Slagle Chairman		



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: City Of Kokomo

UPPAC Database Record ID: 3466

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 7/9/2012

Damage Address: 105 1/2 Elm St, Kokomo, Howard

The Parties

Excavator: City Of Kokomo

Address: 720 E Boulevard, Kokomo, In

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$287

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1206200346

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):


Synopsis: A natural gas line was damaged during excavation for a sewer line.

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 11/13/2012. The excavator had a valid locate request. The operator failed to provide locate marks on a service stub due to inaccurate maps and records.

Conclusion: There was a failure to provide locate markings.

	_			Protection	Advisory
Committee	e Recomm	enda	ation to	IURC	
Respondent: Other Party: Case No.: Date of Advis	ory Meeting:	3479	lex Incor	porated	
Statutes Alleg IC 8-1-26-18(-	l:			
Violation No	Violation				
Recommended 1/Q10					
Additional Inf	ormation: <u>Da</u>	pp ab	stains		

					The state of the s
APPROVED:	X				
(initialed)	Rick Slagle	Alexandria (No. St. St. St. St. St. St. St. St. St. St			
	Chairman				





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Gradex Incorporated

UPPAC Database Record ID: 3479

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 5/11/2012

Damage Address: 690 E Main St Apt 2, Russiaville, Howard

The Parties

Excavator: Gradex Incorporated

Address: 12900 N Meridian St., Suite 120, Carmel, In 46032

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1137.06

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1204260417

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for drainage and road work:

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 10/9/2012. The excavator had a valid locate request however, the operator failed to accurately locate the gas facility.

Conclusion: There was a failure to provide accurate locate markings.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC **NIPSCO** Respondent: Other Party: Key Concrete, Inc. Case No.: 3487 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: (Second) raining Additional Information: APPROVED: Rick Slagle (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Key Concrete, Inc.

UPPAC Database Record ID: 3487

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 7/17/2012

Damage Address: 4006 Vail Ct, Fort Wayne, Allen

The Parties

Excavator: Key Concrete, Inc.

Address: 430 Lower Huntington Rd, Po Box 9279, Fort Wayne, In, 46819

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$879

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207120225

Original Start Date:

Locate Instructions:


Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for road work.

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 10/18/2012. The excavator had a valid locate however, the operator failed to accurately locate the facility.

Conclusion: The locating contractor could not locate the facility and turned the job over to the operator. The operator failed to accurately locate the natural gas facility.

Indiana Undergro Committee Recom			Advisory
Respondent: Other Party: Case No.: Date of Advisory Meetin	Ber) 3493		
Statutes Allegedly Violat IC 8-1-26-18(f)	ed:		
Violation No Violation			
Recommended Penalty:	LCone		
Additional Information:			
APPROVED:	•		
(initialed) Rick Slag Chairman	le		





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Berry-it, Inc.

UPPAC Database Record ID: 3493

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/2/2012

Damage Address: 800 E & N Of 25 N, Knox, Starke

The Parties

Excavator: Berry-it, Inc.

Address: 225 W 450 N, Kokomo, In, 46901

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Trencher

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207313591

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation for a telecommunication line.

Findings: Reported by NIPSCO; excavator failed to respond to initial notice. The excavator had a valid locate request however, the operator failed to locate the unknown stub due to inaccurate maps and records.

Conclusion: There was a failure to locate the natural gas service stub.

Indiana	Undergrou	ınd	Plant	Protection	Advisory
Committe	e Recomm	enda	tion to	IURC	
Respondent: Other Party: Case No.:	Markins	3502	ana Cor	ntracting Comp	any
Date of Advis	sory Meeting:	May 2	21, 2013	•	
Statutes Alleg IC 8-1-26-18 Violation	(f)	l:			
·					
Recommende		Cons			
)					
Additional Int	formation:				
Procedure of the Control of the Cont					

APPROVED					
(initialed)	Rick Slagle Chairman				



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Michiana Contracting Company

UPPAC Database Record ID: 3502

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 7/10/2012

Damage Address: Niles & Lasalle, South Bend, St Joseph

The Parties

Excavator: Michiana Contracting Company

Address: Po Box 929, Plymouth, In 46563

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Auger

Type of Work Performed: Pole

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 2

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1513

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1206261230

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to install a street light pole.

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 10/8/2012. The excavator had a valid locate request. The operator reported the natural gas line was accurately located. The excavator reported the locate markings to be between four (4) and five (5) feet off. The excavator provided a picture which supports their claim.

Conclusion: There was a failure to provide accurate locate markings.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **NIPSCO** Other Party: R and R Excavating Case No.: 3504 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: Training (second Additional Information: APPROVED: Rick Slagle (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: R And R Excavating

UPPAC Database Record ID: 3504

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 7/23/2012

Damage Address: 20170 Kern Rd, South Bend, St Joseph

The Parties

Excavator: R And R Excavating

Address: 2010 Wendt Ave, Mishawaka, In 46545

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Grader/Scraper

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$467

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207122413

Original Start Date:

Locate Instructions:


Follow-Up Locate Instructions (if applicable):


Synopsis: A natural gas service stub was damaged during excavation for road work.

Findings: Reported by NIPSCO; excavator's response to initial notice was received on 10/12/2012. The excavator had a valid locate request. The operator failed to locate a service stub due to inaccurate maps and records.

Conclusion: There was a failure to provide accurate locate markings.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC **NIPSCO** Respondent: Other Party: Hi Speed Utility Case No.: 3522 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: (Second) Training Additional Information: APPROVED: < Rick Slagle (initialed)







http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Hi Speed Utility

UPPAC Database Record ID: 3522

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 7/30/2012 1:09:41 PM

Damage Address: S Park Rd, Kokomo, Howard

The Parties

Excavator: Hi Speed Utility

Address: 2020 Zettler Road, Columbus, Oh 43232

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas Facility Function: Service/Drop

Type of Equipment: Directional Drilling Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207180142

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation to install a telecommunications line.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice. The excavator had a valid locate request however, the operator failed to provide accurate locate markings.

Conclusion: There was a failure to provide accurate locate markings.

Indiana Undergr	ound Plant Protection Advisory
Committee Recom	nmendation to IURC
Respondent: Other Party: Case No.: Date of Advisory Meeting	NIPSCO Indiana Earth, Inc. 3526 ng: May 21, 2013
Statutes Allegedly Viola IC 8-1-26-18(f)	ated:
Violation No Violation	1
Recommended Penalty:	Second
Additional Information:	
APPROVED: Rick Slav	ole



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Indiana Earth, Inc.

UPPAC Database Record ID: 3526

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 7/31/2012 2:20:30 PM

Damage Address: 1045 W Washington St, South Bend, St Joseph

The Parties

Excavator: Indiana Earth, Inc.

Address: 10343 Mckinley Highway, Osceola, In 46561

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$379

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207253092

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 10/22/2012. The excavator had a valid locate request however, the operator failed to locate the abandoned service stub.

Conclusion: There was a failure to provide accurate locate markings.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **NIPSCO** Other Party: Berry-It, Inc. Case No.: 3528 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty; Additional Information: APPROVED: Rick Slagle (initialed)

http://www.in.gov/iure Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Berry-it, Inc.

UPPAC Database Record ID: 3528

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/2/2012 11:55:37 AM

Damage Address: 6055 N 800 E, Knox, Starke

The Parties

Excavator: Berry-it, Inc.

Address: 225 West 450 North, Kokomo, In 46901

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Trencher

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207252779

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service stub was damaged during excavation to install a telecommunications line.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice. The excavator had a valid locate request however; the operator failed to provide accurate locate markings due to inaccurate maps and records.

Conclusion: There was a failure to locate a service stub due to inaccurate maps and records.

Indiana Undergro	ound	Plant	Protection	Advisory
Committee Recom	mend	ation to	IURC	
Respondent: Other Party: Case No.:			at Eagle's Pointe	e, LLC
Date of Advisory Meetin	g: May	21, 2013		
Statutes Allegedly Violat IC 8-1-26-18(f)	ted:			
Violation No Violation			•	
Recommended Penalty:	SCO	nd)		
Additional Information: _				
			···	
APPROVED: Rick Slag Chairman				

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: The Estates At Eagle's Pointe, Llc

UPPAC Database Record ID: 3531

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/2/2012 1:54:29 PM

Damage Address: S Lincoln St, Peru, Miami

The Parties

Excavator: The Estates At Eagle's Pointe, Llc

Address: 2002 Shaw Avenue, Peru, In 46970

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$237

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207242930

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 10/4/2012. The excavator had a valid locate request however, the operator failed to locate the natural gas facility.

Conclusion: The operator failed to accurately locate the natural gas facility.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: Vectren Other Party: Reynolds, Inc. Case No.: 3535 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: Training Additional Information: Slagle abstains **APPROVED:** (initialed) Dan Meiners



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Reynolds, Inc.

UPPAC Database Record ID: 3535

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 8/1/2012 1:07:49 PM

Damage Address: Whiteland Rd, Bargersville, Johnson

The Parties

Excavator: Reynolds, Inc.

Address: 4520 N In Rt 37, Po Box 186, Orleans, In 47452

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 6

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$11138

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207191209

Original Start Date:

Locate Instructions:


Follow-Up Locate Instructions (if applicable):

Synopsis: A 4" natural gas line was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice. The excavator had a valid locate request however, the operator failed to locate the natural gas facility.

Conclusion: There was a failure to provide locate markings.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: Vectren Other Party: **United Infrastructure LLC** Case No.: 3537 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: Second mainine Additional Information: Slagle abstains APPROVED: Dan Meiners (initialed)





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: United Infrastructure LLC

UPPAC Database Record ID: 3537

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 8/1/2012 4:03:35 PM

Damage Address: Greenfield Ave, Noblesville, Hamilton

The Parties

Excavator: United Infrastructure Llc

Address: Po Box 611, Westfield, In 46074

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Drainage

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$549

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207271246

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for drainage.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice. The excavator had a valid locate request however, the operator failed to locate the facility.

Conclusion: There was a failure to locate the natural gas facility.

Indiana Undergrou Committee Recomm	and Plant Protection Advisor nendation to IURC	СУ
Respondent: Other Party: Case No.: Date of Advisory Meeting:	NIPSCO B & D Sewer And Backhoe Service 3538	
Statutes Allegedly Violated IC 8-1-26-18(f) Violation No Violation	d:	
Recommended Penalty:	econd)	
Additional Information:		
		_
APPROVED: (initialed) Rick Slagle Chairman		

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: B & D Sewer And Backhoe Service

UPPAC Database Record ID: 3538

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/2/2012 9:25:22 AM

Damage Address: 8444 Valley View Dr, Lowell, Lake

The Parties

Excavator: B & D Sewer And Backhoe Service

Address: 531 Winston Ct, Schererville, In 46375

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1207262343

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 10/1/2012. The excavator provided notice of excavation on 8/2/12 but the operator failed to provide locate markings due to inadequate maps and records.

Conclusion: The operator failed to provide locate markings.

Indiana Undergrou				Advisory
Committee Recomm	ienda	tion to	IURC	
Respondent: Other Party: Case No.: Date of Advisory Meeting:	3541	Fehring		
Statutes Allegedly Violated IC 8-1-26-18(f)	1:			
Violation No Violation				
Recommended Penalty: Training (Sc	2 On	el)		
Additional Information:				
·				······································
APPROVED: (initialed) Rick Slagle Chairman				



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Rick Fehring

UPPAC Database Record ID: 3541

Report Date: 4/18/2013

Investigator: Mike Orr

Damage Date: 8/7/2012 12:45:06 PM

Damage Address: 9518 Marigold Ln, Munster, Lake

The Parties

Excavator: Rick Fehring

Address: 9518 Marigold Ln, Munster, In 46321

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Unknown/Other

Type of Work Performed: Fencing

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates:

Indiana 811 Ticket Number: 1207313709

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a fence post.

Findings: Reported by Indiana 811; excavator failed to respond to initial notice. The property owner had a valid locate request however, the operator failed to provide accurate locate marks. The tracer wire had separated from the pipe.

Conclusion: There was a failure to provide accurate locate markings.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: Vectren Other Party: Precision Utilities Group, Inc. Case No.: 3543 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-18(f) Violation No Violation Recommended Penalty: MINIM Additional Information: Slagle abstains APPROVED: Dan Meiners (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Precision Utilities Group Inc

UPPAC Database Record ID: 3543

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/7/2012 9:32:52 PM

Damage Address: 6450 E Haythorne Ave, Terre Haute, Vigo

The Parties

Excavator: Precision Utilities Group Inc

Address: 5714 Saint Joe Road, Ft Wayne, In 46835

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Boring

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 6

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$3109

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1208012027

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A four inch (4") plastic gas line was damaged during excavation for a telecommunications line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 9/27/2012. The excavator had a valid locate request however, the operator failed to locate the Natural gas facility.

Conclusion: There was a failure to locate the natural gas facility.

9	ınd Plant Protection Advisory
Committee Recomm	nendation to IURC
Respondent:	NIPSCO
Other Party:	QC Communications, Inc.
Case No.:	3545
Date of Advisory Meeting:	
Statutes Allegedly Violated	1:
IC 8-1-26-18(f)	
Violation No Violation	
Recommended Penalty: (S	second)
Additional Information:	
	
APPROVED:	
(initialed) Rick Slagle	
Chairman	

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: QC Communications, Inc.

UPPAC Database Record ID: 3545

Report Date: 4/19/2013

Investigator: Mike Orr

Damage Date: 8/8/2012 1:04:19 PM

Damage Address: Us Rt 6, Nappanee, Elkhart

The Parties

Excavator: QC Communications, Inc.

Address: 7925 West 100 South, Wabash, In 46992

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Boring

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries:

Fatalities:

Repair Cost (if known): \$1527

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1208022736

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a telecommunication line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 9/26/2012. The excavator had a valid locate request however, the operator failed to provide accurate locate marks.

Conclusion: There was a failure to provide accurate locate markings.

	Underground ee Recommen			Advisory
Respondent: Other Party: Case No.: Date of Adv	Ci	owen Constr itizens Gas 58 ay 21, 2013	ruction	
Statutes Alle	egedly Violated: 6(g)			
Violation N	No Violation			
Recommend Warn	ed Penalty:			
Additional In	nformation: Warr	en abstains		
APPROVE (initialed)	Pick Slagle Chairman			

http://www.in.gov/iurc Office; (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Bowen Construction

UPPAC Database Record ID: 3758

Report Date: 04/03/2013

Investigator: Howard Friend

Damage Date: 7/12/2012

Damage Address: 3800 W Southport Rd, Indianapolis, Marion County

The Parties

Excavator: Bowen Construction (Contractor)

Address: 8002 N Meridian St, Indianapolis, In 46260

Facility Owner: Citizens Gas

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Electric

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for an electric line.

Findings: Reported by Tony Chan (Citizens Gas); excavator's response to initial notice was received on 1/22/2013. The excavator reported a locate request dated 5/16/12, 57 days prior to the damage.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

	Undergrou e Recomm			Protection IURC	Advisory
Respondent: Other Party: Case No.: Date of Advi	sory Meeting:	Vectre 4067		ction	
Statutes Alle IC 8-1-26-20	gedly Violated (a)(2)	:			
Violation N	o Violation				
Recommende () () () ()	ed Penalty:	Her			
Additional In	formation: <u>Sla</u>	gle abst	tains		
				Allekan yang Marian Malangaran Kanalan ang ang ang ang ang ang ang ang ang a	
APPROVED (initialed)	Dan Meiners	iel J	Me	irus	



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: JBI Construction

UPPAC Database Record ID: 4067

Report Date: 04/17/2013

Investigator: William Boyd

Damage Date: 10/29/2012 9:01:04 AM

Damage Address: Outer Lincoln Ave, Newburgh, Warrick County

The Parties

Excavator: JBI Construction (Contractor)

Address: 10335 Hedden Road, Evansville, In 47725

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1600

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1210153923

Original Start Date:

Locate Instructions: LOCATE FROM THE INTERSECTION GOING EAST APPROX 1000 FEET TO FRAME ROAD RIGHT OF WAY TO RIGHT OF WAY

Follow-Up Locate Instructions (if applicable):

Synopsis: Excavator damaged 2" plastic gas main during to install storm sewers and inlet boxes.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 12/28/2012. Excavator possessed a valid locate request but got into the main with the bucket of the trackhoe while attempting to loosen rock in the excavation.

Conclusion: Excavator failed to maintain the required clearance from the gas facility.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: John Ferguson Other Party: **NIPSCO** Case No.: 4119 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty; Warnin Additional Information: APPROVED: Rick Slagle (initialed)

Chairman



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: John Ferguson

UPPAC Database Record ID: 4119

Report Date: 3/21/2013

Investigator: Howard Friend

Damage Date: 11/14/2012 3:51:48 PM

Damage Address: 10647 Mckinley Hwy, Osceola, St Joseph

The Parties

Excavator: John Ferguson

Address: 10647 Mckinley Hwy, Osceola, In 46561

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Irrigation

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1210192105

Original Start Date:

Locate Instructions: Locate entire property out to the retention swale and entire property -from the north building from the new panel to the old panel

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for irrigation.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 1/25/2013. The excavator provided notice of excavation on 10/19/12 and damaged the line 26 days later.

Conclusion: The excavator failed to provide notice of excavation within the twenty (20) calendar days of excavation.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

	0	ınd Plant endation to	Protection	Advisory
Commute	e Kecomm		TURC	,
Respondent:		NIPSCO-(<u> </u>	
Other Party:		NIPSCO		
Case No.:		4228		
	sory Meeting:	May 21, 2013	3	
Statutes Alleg	gedly Violated	l:		
IC 8-1-26-20	(a)(2)			
Violation	o Violation			
Recommende	d Penalty:	econd)		
A 11''.' 1 T	.	•		
Additional In	formation:		· · · · · · · · · · · · · · · · · · ·	
			Photo-Ad-Mills - Ad-Mills - Company - The Co	
APPROVED	: PS			
(initialed)	Rick Slagle			
	Chairman			

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Northern Indiana Public Service Company

UPPAC Database Record ID: 4228

Report Date: 3/21/2013

Investigator: Howard Friend

Damage Date: 11/19/2012 10:52:05 AM

Damage Address: 180 Palomino Ln, Valparaiso, Porter

The Parties

Excavator: Northern Indiana Public Service Company

Address: 22 South In Rt 49, Valparaiso, In 46383

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 6

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1211142731

Original Start Date:

Locate Instructions: Locate the entire property from the gas riser to the main and from the electric meter to the pole--path is flagged

Follow-Up Locate Instructions (if applicable):

Synopsis: A two (2) inch natural gas line was damaged during excavation to install a gas service.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/15/2013. The excavator had a valid locate request and the operator had accurate locate marks. There was a failure to maintain clearance with mechanized equipment.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Committee Recommendation to IURC **Case Construction** Respondent: Other Party: Vectren Case No.: 4240 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation) No Violation Recommended Penalty: Training Additional Information: Slagle abstains APPROVED: Dan Meiners (initialed) Vice Chairman

Underground Plant Protection Advisory

Indiana



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Case Construction

UPPAC Database Record ID: 4240

Report Date: 3/22/2013

Investigator: Howard Friend

Damage Date: 11/26/2012 10:42:00 AM

Damage Address: 1517 6th St, Bedford, Lawrence

The Parties

Excavator: Case Construction

Address: 4004 W Willoughby Drive, Edinburgh, In 46124

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$209

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1210312072 - EXPIRED Original Start

Date:

Locate Instructions: Locate at previous street cuts on 6th and the alley east of p--please paint

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to repair a street cut.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 2/25/2013. The excavator provided notice of excavation on 10/31/12 and damaged the line twenty six (26) days later. The excavator reported the damage was above ground. The original locate markings were still visible at the time of the damage.

Conclusion: The excavator failed to maintain an active locate request.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **Case Construction** Other Party: Vectren Case No.: 4244 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty: Training Additional Information: Slagle abstains APPROVED: (initialed) Dan Meiners

http://www.in.gov/iure Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Case Construction

UPPAC Database Record ID: 4244

Report Date: 3/22/2013

Investigator: Howard Friend

Damage Date: 11/27/2012 7:48:31 AM

Damage Address: 2614 S Rogers St, Bloomington, Monroe

The Parties

Excavator: Case Construction

Address: 4004 W Willoughby Drive, Edinburgh, In 46124

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Road Work

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$689

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1211081646

Original Start Date:

Locate Instructions: Locate at previous 10x10 6x5 driveway and 3x5 sidewalk cut at address-- please paint

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to repair a street cut.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 2/25/2013. The excavator provided notice of excavation and the operator provided accurate locate markings. The problem is the excavator provided very specific location instructions and then dug outside of the located area.

Conclusion: The excavator failed to provide adequate locate information..

Violation: 8-1-26-16(g)(out) Failure to provide notice of excavation - damage occurred outside requested locate area.

Indiana Undergro				Advisory
Committee Recom	mend	ation to	IURC	
Respondent: Other Party: Case No.: Date of Advisory Meetin	NIP: 4250	SCO Î	e Tree Service	
Statutes Allegedly Violatics IC 8-1-26-16(g)	ted:			
Violation No Violation				
Recommended Penalty:	Her			
Additional Information:	·			
APPROVED:				
(initialed) Rick Slag Chairman				



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Mark Temple Tree Service

UPPAC Database Record ID: 4250

Report Date: 3/26/2013

Investigator: Howard Friend

Damage Date: 11/28/2012 2:36:03 PM

Damage Address: 803 Northwood Dr, South Bend, St Joseph

The Parties

Excavator: Mark Temple Tree Service

Address: 28296 Inwood Road, North Liberty, In 46554

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Unknown/Other

Type of Work Performed: Landscaping

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions: Locate-- the east side of the property

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged while grinding tree stumps in preparation to plant a tree.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 2/21/2013. The excavator was using mechanized equipment and failed to provide notice of excavation.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: Blankenberger Brothers Other Party: Vectren Case No.: 4260 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation No Violation Recommended Penalty: arning Additional Information: Slagle abstains APPROVED: Dan Meiners (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Blankenberger Brothers

UPPAC Database Record ID: 4260

Report Date: 3/27/2013

Investigator: Howard Friend

Damage Date: 12/4/2012 8:30:13 AM

Damage Address: Cave Ave, Evansville, Vanderburgh

The Parties

Excavator: Blankenberger Brothers

Address: 11700 Water Tank Road, Cynthiana, In 47612

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$463

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1211263386

Original Start Date:

Locate Instructions: From Harmony Way locate the right-of-way on both sides of Cave Ave going east approximately 800 feet ending at Hurst Ave

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/12/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator failed to expose the gas facility before using mechanized equipment.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **Custom Concrete** Other Party: Vectren Case No.: 4267 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty: Additional Information: Slagle abstains **APPROVED:** Dan Meiners (initialed) Vice Chairman



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Custom Concrete

UPPAC Database Record ID: 4267

Report Date: 3/27/2013

Investigator: Howard Friend

Damage Date: 12/5/2012 3:08:50 PM

Damage Address: 3112 Underwood Dr, Whiteland, Johnson

The Parties

Excavator: Custom Concrete

Address: 17241 Foundation Parkway, Westfield, In 46074

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Curb / Sidewalk.

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$388

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1211072463

Original Start Date:

Locate Instructions: locate entire property

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for curbs and sidewalks.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/6/2013. The excavator provided notice of excavation on 11/7/12 and damaged the line 28 days later. The excavator has attended training with Mr. Baker and has requested this case be closed.

Conclusion: There was a failure to provide notice of excavation, expired ticket.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **Cameron Beer** Other Party: Vectren Case No.: 4271 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation No Violation Recommended Penalty: Additional Information: Slagle abstains **APPROVED:** (initialed) Dan Meiners



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Cameron Beer

UPPAC Database Record ID: 4271

Report Date: 3/27/2013

Investigator: Howard Friend

Damage Date: 12/10/2012 7:33:21 AM

Damage Address: 3983 W 241st St, Sheridan, Hamilton

The Parties

Excavator: Cameron Beer

Address: 1608 Northbrook Dr, Indianapolis, In 46260

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$225

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1212052208

Original Start Date:

Locate Instructions: At the above address--locate the entire property

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/5/2013. The excavator, a friend of the property owner, had a valid locate request. The operator provided accurate locate markings. While working all night trying to help a friend they damaged the gas line.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Indiana	Undergrou	nd	Plant	Protectio	n Advisory
Committe	ee Recomm	enda	tion to	IURC	
Respondent: Other Party: Case No.: Date of Advi	sory Meeting:	NIPS 4278		ting	
Statutes Alle IC 8-1-26-16	gedly Violated (g)	:			
Violation	o Violation				
Recommend	1 - 1 1	V			
Additional In	nformation:				
APPROVEI): <u>\$</u>				
(initialed)	Rick Slagle Chairman			·	



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Pelley Excavating

UPPAC Database Record ID: 4278

Report Date: 3/27/2013

Investigator: Howard Friend

Damage Date: 12/11/2012 10:38:22 AM

Damage Address: 2016 Frederickson St, South Bend, St Joseph

The Parties

Excavator: Pelley Excavating

Address: 1990 Progressive Dr, Niles, Mi 49120

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Demolition

Damage Impact

Product Release: Yes Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0 Fatalities: 0 Repair Cost (if known): \$198

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes Indiana 811 Ticket Number: 1211130352 Original Start Date:

Locate Instructions: Locate the entire property Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during demolition of a house.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/8/2013. The excavator provided notice of excavation on 11/13/12 and damaged the line twenty (28) days later.

Conclusion: There was a failure to provide notice of excavation, expired ticket.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Indiana Underground Plant Protection Advisory Committee Recommendation to IURC **QC** Communications Inc Respondent: Other Party: Vectren Case No.: 4279 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation) No Violation Recommended Penalty: Training Additional Information: Slagle abstains APPROVED: (initialed) Dan Meiners Vice Chairman





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Qc Communications Inc

UPPAC Database Record ID: 4279

Report Date: 3/27/2013

Investigator: Howard Friend

Damage Date: 12/11/2012 2:46:29 PM

Damage Address: Branigin Creek Blvd, Franklin, Johnson

The Parties

Excavator: Qc Communications Inc

Address: 7925 West 100 South, Wabash, In 46992

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Directional Drilling

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1044

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1212031934

Original Start Date:

Locate Instructions: Starting at 2606 Branigin Creek Blvd - locate east 1000 feet along the north side of road

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during directional boring to install a cable.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/6/2013. The excavator had a valid locate request. The operator provided accurate locate markings. The excavator failed to expose the gas facility at the point of intersection with the bore.

Conclusion: There was a failure to maintain clearance.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Indiana	Undergrou	ind	Plant	Protection	ı Advisory
Committe	ee Recomm	ienda	ition to	IURC	
Respondent: Other Party: Case No.:		NIPS 4301	SCO SCO	City Utilities	
Date of Adv	isory Meeting:	May	21, 2013		
Statutes Alle IC 8-1-26-26	gedly Violated O(a)(2)	1:		•	
Violation N	lo Violation			·	
Recommend	, -				
			anggan Magada ay da kaganilag ay da galika		
Additional Ir	nformation:				
APPROVEI): F				
(initialed)	Rick Slagle				
	Chairman				

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile; (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Fort Wayne City Utilities

UPPAC Database Record ID: 4301

Report Date: 3/28/2013

Investigator: Howard Friend

Damage Date: 12/19/2012 9:31:58 AM Damage Address: 820 Nuttman Ave, Wayne, Allen

The Parties

Excavator: Fort Wayne City Utilities

Address: 415 E Wallace St, Fort Wayne, In 46803

Facility Owner: NIPSCO

Pipeline Facility

Facility Function: Service/Drop Facility Type: Natural Gas

Type of Equipment: Backhoe/Trackhoe Type of Work Performed: Water

Damage Impact

Product Release: Yes Ignition: No

Number of Customers Affected: 1 Service Interruption: True

Repair Cost (if known): \$ Injuries: 0 Fatalities: 0

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes Indiana 811 Ticket Number: 1212061369 Original Start Date: 12/10/12

Locate Instructions: In front of the address on the north side of the street

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/15/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The service was "looped" past the main, meaning the service started out going the opposite way from the house and then circled back. The service was damaged at the loop but was still within twenty four (24) inches of the locate markings.

Conclusion: There was a failure to maintain clearance.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Underground Plant Protection Indiana Advisory Committee Recommendation to IURC Respondent: **Benjamin Franklin Plumbing** Other Party: Vectren Case No.: 4309 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation \ No Violation Recommended Penalty: arnina Additional Information: Slagle abstains APPROVED: (initialed) Dan Meiners

Vice Chairman

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Benjamin Franklin Plumbing

UPPAC Database Record ID: 4309

Report Date: 3/28/2013

Investigator: Howard Friend

Damage Date: 1/2/2013 3:08:11 PM

Damage Address: 1482 Fry Rd, White River, Johnson

The Parties

Excavator: Benjamin Franklin Plumbing

Address: 1551 South Franklin Road, Indianapolis, In 46239

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$650

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1212310600

Original Start Date: 1/2/2013

Locate Instructions: At the above address--locate the entire driveway

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 2/19/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator reported they had saw cut the blacktop and was in the process of using shovels to expose the gas service. The pictures provided by the operator clearly show the mini-backhoe bucket in the hole at the time of the damage.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

	0	ind Plant endation to	IURC	Advisory
Respondent: Other Party: Case No.: Date of Advi	sory Meeting:	Infrasource U NIPSCO 4329 May 21, 2013	nderground Co	nstruction
Statutes AllegIC 8-1-26-16	gedly Violated (g)	1:		
Violation N	o Violation			
Recommende	ed Penalty:	Her		
Additional In	formation:			
APPROVED (initialed)	e: Rick Slagle			
	Chairman			

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Infrasource Underground Construction

UPPAC Database Record ID: 4329

Report Date: 4/8/2013

Investigator: Howard Friend

Damage Date: 1/15/2013 12:16:55 PM

Damage Address: W 105th Ct, Center, Lake

The Parties

Excavator: Infrasource Underground Construction

Address: 4033 Morgan Road, Ypsilanti, Mi 48197

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 3

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1212030929

Original Start Date:

1/16/2013Locate Instructions: This is for addresses 4807 4806 and 4802 west 105th Court -- locate the entire property and both sides of west 105th Court for all three properties

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a natural gas line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/11/2013. The excavator was working for the operator and was digging after one locate request had expired and prior to one locate being active.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **Sun Communications** Other Party: **NIPSCO** Case No.: 4336 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(1) Violation No Violation Recommended Penalty: (Sccond Additional Information: APPROVED: (initialed) Rick Slagle

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Sun Communications

UPPAC Database Record ID: 4336

Report Date: 4/8/2013

Investigator: Howard Friend

Damage Date: 1/23/2013 1:18:45 PM

Damage Address: Bent Creek Rd, Center, Howard

The Parties

Excavator: Sun Communications

Address: 17728 Sun Park Drive, Westfield, In 46074

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Boring

Type of Work Performed: Electric

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 9

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1301170355

Original Start Date:

Locate Instructions: Starting at the northwest corner of the intersection at the secondary ped - locate going east for 60 feet across toubey pike and locate going north for 150 feet along the white flagged route

Follow-Up Locate Instructions (if applicable):

Synopsis: A two (2) inch natural gas main was damaged while boring for a new electric line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 3/18/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator's employees failed to expose the natural gas facility under a concrete sidewalk prior to making the bore. The excavator provided documentation that the two (2) employees had been disciplined for not exposing the gas facility.

Conclusion: There was a failure to plan excavation to avoid damage.

Violation: 8-1-26-20(a)(1) Failure to plan excavation to avoid damage or interference with underground facilities.

Committee Recomm	and Plant Protection nendation to IURC	Advisory
Respondent: Other Party: Case No.: Date of Advisory Meeting:	Nixco Plumbing Sycamore Gas Company 4359 May 21, 2013	
Statutes Allegedly Violated IC 8-1-26-16(g)	d:	
Violation No Violation		
Recommended Penalty:	y ·	
Additional Information:		
APPROVED: Rick Slagle Chairman		



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Nixco Plumbing

UPPAC Database Record ID: 4359

Report Date: 3/28/2013

Investigator: Howard Friend

Damage Date: 12/17/2012

Damage Address: 34 Pebble Beach Ln, Lawrenceburg, In, 47025

The Parties

Excavator: Nixco Plumbing

Address: 4281 Sr 42, Mason, Oh 45040

Facility Owner: Sycamore Gas Company

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 4

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$350

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to repair a water leak.

Findings: Reported by Aaron Lambert; excavator's response to initial notice was received on 3/7/2013. Locate markings had been provided for a different excavator. Due to a communication error, proper notice of excavation did not occur.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: **Rieth Riley Construction Company** Other Party: **NIPSCO** Case No.: 4362 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(1) Violation No Violation Recommended Penalty (Second) Additional Information: APPROVED: < Rick Slagle (initialed)

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Rieth Riley Construction Company

UPPAC Database Record ID: 4362

Report Date: 3/26/2013

Investigator: Howard Friend

Damage Date: 8/23/2012

Damage Address: E. 4th Ave., Gary, Lake

The Parties

Excavator: Rieth Riley Construction Company

Address: Po Box 477, Goshen, In 46527

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Hand Tools

Type of Work Performed: Curb / Sidewalk

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1208211652

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):


Synopsis: A two (2) inch plastic gas main was damaged by a forming stake during excavation for a concrete curb.

Findings: Reported by Tommy Buher (NIPSCo); excavator's response to initial notice was received on 3/22/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator reports that INDOT indicated the gas facilities are located in the construction zone, but should not be in conflict because of the required depth. The contract also included the name and contact phone number of the NIPSCO employee to call with questions should a possible conflict arise. The excavator failed to expose the gas facility to verify the actual depth prior to driving in a form stake.

Conclusion: There was a failure to plan excavation to avoid damage or interference with underground facilities. The depth of the facility should have been verified.

Violation: 8-1-26-20(a)(1) Failure to plan excavation to avoid damage or interference with underground facilities.

Indiana Undergrou Committee Recomm			Advisory
Respondent: Other Party: Case No.: Date of Advisory Meeting:	Krooswyk Tru NIPSCO 4364 May 21, 2013	cking and Exc	avating, Inc.
Statutes Allegedly Violated IC 8-1-26-16(g)	1:		
Violation No Violation			
Recommended Penalty:	· · · · · · · · · · · · · · · · · · ·		
Additional Information:			
APPROVED: Rick Slagle		·	· .





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Krooswyk Trucking And Excavating Inc

UPPAC Database Record ID: 4364

Report Date: 3/13/2013

Investigator: Howard Friend

Damage Date: 9/26/2012

Damage Address: 2011 Main St, Highland, Lake

The Parties

Excavator: **Krooswyk Trucking And Excavating Inc** Address: 9731 Indianapolis Blvd, Highland, In 46322

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Demolition

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during demolition of a building.

Findings: Reported by Tommy Buher (NIPSCo); excavator's response to initial notice was received on 3/7/2013. The excavator failed to provide notice of excavation and reported the contractor that hired him was responsible to provide notice of excavation. He also reported the operator should have retired the facility. The operator reported the line was located, but for a different contractor.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Indiana Undergro	und Plant	Protection	Advisory
Committee Recomm	nendation to	IURC	
Respondent: Other Party: Case No.: Date of Advisory Meeting	Bender Const NIPSCO 4366 : May 21, 2013		
Statutes Allegedly Violate IC 8-1-26-16(g)	d:		
Violation No Violation			
Recommended Penalty:	er		
Additional Information:			
APPROVED: Rick Slagle)		
Chairman			

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Bender Construction Inc

UPPAC Database Record ID: 4366

Report Date: 3/22/2013

Investigator: Howard Friend

Damage Date: 10/17/2012

Damage Address: 704 W Lasalle, Mishawaka, St. Joseph

The Parties

Excavator: Bender Construction Inc

Address: 63558 Cr 31, Goshen, In, 46528

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Curb / Sidewalk

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$521

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation to install a curb/walk.

Findings: Reported by Steve Noffsinger (NIPSCo); excavator's response to initial notice was received on 3/6/2013. The excavator failed to provide notice of excavation. The excavator damaged the line with a concrete form stake.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Woodruff and Sons Respondent: Other Party: **NIPSCO** Case No.: 4368 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(1) Violation No Violation Recommended Penalty: (second mining Additional Information: APPROVED: < Rick Slagle (initialed)

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Woodruff And Sons

UPPAC Database Record ID: 4368

Report Date: 3/13/13

Investigator: Howard Friend

Damage Date: 10/17/2012

Damage Address: 523 E 8th St, Michigan City, Laporte

The Parties

Excavator: Woodruff And Sons

Address: P.o. Box 450, Michigan City, In 46361

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1210013362

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer.

Findings: Reported by Carrie Ludwig (NIPSCo); excavator's response to initial notice was received on 2/25/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator exposed a retired gas line and assumed that was the marked facility. The active gas line was under the retired line and was damaged with a backhoe.

Conclusion: There was a failure to plan excavation to avoid damage

Violation: 8-1-26-20(a)(1) Failure to plan excavation to avoid damage or interference with underground facilities.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC William Molnar Respondent: Other Party: **NIPSCO** Case No.: 4396 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty; Warning letter Additional Information: APPROVED: Rick Slagle (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: William Molnar

UPPAC Database Record ID: 4396

Report Date: 4/18/2013

Investigator: Howard Friend

Damage Date: 11/3/2012

Damage Address: 61570 Kingston Ct, South Bend, St Joseph

The Parties

Excavator: William Molnar

Address: 61570 Kingston Ct, South Bend, In 46614

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Pole

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation to install a mailbox post.

Findings: Reported by Carrie Ludwig (NIPSCo); excavator's response to initial notice was received on 4/18/2013. The excavator/homeowner failed to provide notice of excavation.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Indiana Underground Plant Protection Advisory Committee Recommendation to IURC Respondent: **Geiger Excavating** Other Party: **NIPSCO** Case No.: 4407 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty: Training Additional Information: APPROVED: Rick Slagle (initialed) Chairman

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Geiger Excavating

UPPAC Database Record ID: 4407

Report Date: 3/28/2013

Investigator: William Boyd

Damage Date: 12/30/2012

Damage Address: 829 Van Buren St., Auburn, Dekalb

The Parties

Excavator: Geiger Excavating

Address: 811 Airport North Office Park, Fort Wayne, In 46825

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: No

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1212052856 - EXPIRED Original Start

Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):


Synopsis: A natural gas main was damaged during excavation for a sewer project.

Findings: Reported by Tommy Buher (NIPSCo); excavator's response to initial notice was received on 3/18/2013. The excavator damaged the gas main while working with an expired locate ticket.

Conclusion: There was a failure to provide notice of excavation, expired ticket.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Hillside Rentals Respondent: Other Party: **NIPSCO** Case No.: 4412 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation) No Violation Recommended Penalty: Warning Additional Information: APPROVED: (initialed) Rick Slagle





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Hillside Rentals

UPPAC Database Record ID: 4412

Report Date: 3/28/2013 Investigator: Howard Friend

Damage Date: 12/17/2012 Damage Address: 1032 Rivermet Ave, Fort Wayne, Allen

The Parties

Excavator: Hillside Rentals

Address: 1032 Rivermet Ave, Fort Wayne, In 46805

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe Type of Work Performed: Sewer

Damage Impact

Product Release: Yes Ignition: No

Service Interruption: True Number of Customers Affected: 2

Injuries: 0 Fatalities: 0 Repair Cost (if known): \$162

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No Indiana 811 Ticket Number: Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):


Synopsis: A natural gas service was damaged during excavation of a sewer line.

Findings: Reported by Tommy Buher (NIPSCo); excavator's response to initial notice was received on 3/18/2013. The excavator failed to provide notice of excavation. They reported the sewer was backing up into the house and they could not wait for two (2) days for a locate.

Conclusion: There was a failure to provide notice of excavation. As a property manager they may face this problem in the future. They need to understand if and when an emergency locate request may be appropriate.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Indiana Underground Plant Protection Advi	sory
Committee Recommendation to IURC	
Respondent: NIPSCO Other Party: Fieldstone Enterprise LLC Case No.: 4426 Date of Advisory Meeting: May 21, 2013	
Statutes Allegedly Violated: IC 8-1-26-18(f)	
Violation No Violation	
Recommended Penalty: (Second)	
Additional Information:	
APPROVED:	
(initialed) Rick Slagle	





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Fieldstone Enterprise Llc

UPPAC Database Record ID: 4426

Report Date: 3/28/2013

Investigator: Howard Friend

Damage Date: 12/18/2012

Damage Address: 529-1 Chicory Ln, Valparaiso, Porter

The Parties

Excavator: Fieldstone Enterprise Llc

Address: 930 N 651 E, Westville, In, 46391

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas line was damaged during excavation for a water line.

Findings: Reported by Steve Noffsinger (NIPSCo); excavator's response to initial notice was received on 3/12/2013. The excavator provided notice of excavation on 11/27/12 and damaged the line twenty one (21) days later. The operator provided incorrect locate markings originally.

Conclusion: There was a failure to provide notice of excavation by allowing the locate request to expire.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Indiana Underground Plant Protection Advisory Committee Recommendation to IURC Mike Swinehart Respondent: Other Party: **NIPSCO** Case No.: 4471 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(1) Violation No Violation Recommended Penalty: Warning Additional Information: APPROVED: . Rick Slagle (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Mike Swinehart

UPPAC Database Record ID: 4471

Report Date: 4/25/2013

Investigator: Howard Friend

Damage Date: 2/14/2013 11:11:55 AM

Damage Address: 2775 N 910 W, Newbury, Lagrange

The Parties

Excavator: Mike Swinehart

Address: 2760 N 900 W, Shipshewana, In 46565

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Hand Tools

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date: 11/26/2012

Locate Instructions: Locate the south side of the house on the property

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 4/18/2013. The excavator/homeowner provided notice of excavation on November 19, 2012 and damaged the line on February 14, 2013. The gas facility was exposed and the excavation began to collapse. The homeowner attempted to shore up the banks and lost control of the material and dropped in on the gas line causing a leak.

Conclusion: There was a failure to protect the gas facility at the excavation site.

Violation: 8-1-26-20(a)(1) Failure to plan excavation to avoid damage or interference with underground facilities.

Underground Plant Protection Advisory Committee Recommendation to IURC **Grimmer Construction Company** Respondent: Other Party: **NIPSCO** Case No.: 4473 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(1) Violation No Violation Recommended Penalty: Additional Information: APPROVED: Rick Slagle (initialed) Chairman

Indiana

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Grimmer Construction Company

UPPAC Database Record ID: 4473

Report Date: 4/18/2013

Investigator: Howard Friend

Damage Date: 2/14/2013 3:03:30 PM

Damage Address: 2nd Ave Nw, Keener, Jasper

The Parties

Excavator: **Grimmer Construction Company**Address: 2619 Main Street, Highland, In 46322

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Water

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1302061096 Original Start Date: 2/8/2013

Locate Instructions: From the west side of the above intersection locate going east along both sides of 2nd avenue northwest from right of way to right of way for approx 600 feet to the centerline of the driveway at the address of 614 2nd avenue northwest

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a water line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 4/11/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator exposed one gas line and reported they accidently covered the marks for a second service and forgot the second line was in place. They damaged the second line as they expanded the excavation site.

Conclusion: There was a failure to plan excavation to avoid damage.

Violation: 8-1-26-20(a)(1) Failure to plan excavation to avoid damage or interference with underground facilities.

	_			Protection	Advisory
Committee	e Recomm	enda	ation to	IURC	
Respondent:		J and	d B Build	lers & Contract	ing Services,
1		Inc.			8
Other Party:		NIPS	SCO	•	
Case No.:		4484			
Date of Advis	ory Meeting:	May	21, 2013		
Statutes Alleg	edly Violated	l:			
IC 8-1-26-16(-				
Violation No	Violation				
Recommended	l Penalty:	fer			
A					
Additional Info	ormation:				
	F-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1				
				·	
				·	
			·		
APPROVED:					
(initialed)	Rick Slagle				
	Chairman				





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: J And B Builders & Contracting Services, Inc

UPPAC Database Record ID: 4484

Report Date: 4/25/2013

Investigator: Howard Friend

Damage Date: 2/25/2013 11:40:42 AM

Damage Address: 11927 Montego Ln, Keener, Jasper

The Parties

Excavator: J And B Builders & Contracting Services, Inc

Address: 5668 E 1168 N, Demotte, In 46310

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1302041991

Original Start Date:

Locate Instructions: This is Island Grove MHP - locate the entire lot number 10 at above address

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a sewer line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 4/10/2013. The excavator provided notice of excavation on 2/4/13 and damaged the natural gas line twenty one (21) days later. The damage occurred on the lot next to the address that had been requested.

Conclusion: There was a failure to provide notice of excavation by allowing the original locate notice to expire. Also, the excavation extended past the original notice address.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Respondent: Miller Pipeline Other Party: Vectren Case No.: 4486 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation) No Violation Recommended Penalty: (as completed May o Training Additional Information: Slagle abstains **APPROVED:** Dan Meiners (initialed)

Vice Chairman

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Miller Pipeline

UPPAC Database Record ID: 4486

Report Date: 4/25/2013

Investigator: Howard Friend

Damage Date: 2/25/2013 4:19:13 PM

Damage Address: S D St, Pipe Creek, Madison

The Parties

Excavator: Miller Pipeline

Address: 8850 Crawfordsville Rd, Indianapolis, In 46234

Facility Owner: Vectren

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$306

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1302181633

Original Start Date:

Locate Instructions: Locate alley between d and e streets

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a gas line.

Findings: Reported by Indiana 811; excavator's response to initial notice was received on 4/12/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator failed to maintain two (2) feet of clearance with mechanized equipment.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Indiana Underground Plant Protection Advisory Committee Recommendation to IURC Respondent: **Art Bunt Homes Inc** Other Party: **NIPSCO** Case No.: 4511 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty; tarnina Additional Information: APPROVED: Rick Slagle (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Art Bunt Homes Inc

UPPAC Database Record ID: 4511

Report Date: 4/25/2013

Investigator: William Boyd

Damage Date: 11/5/2012

Damage Address: 8207 Quincy Dr, Fort Wayne, Allen

The Parties

Excavator: Art Bunt Homes Inc

Address: Po Box 100, Leo, In 46765

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Construction

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$452.18

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1211030083

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):


Synopsis: A natural gas service drop was damaged during excavation related to home construction.

Findings: Reported by Carrie Ludwig (NIPSCo); excavator's response to initial notice was received on 4/16/2013. The excavator did not wait the required 2 working days before beginning excavation. Damage occurred on November 5 and locate ticket was not good until November 8. The excavator also failed to notify Indiana 811 and 911 upon the release of natural gas due to the pipeline damage.

Conclusion: The excavator failed to provide adequate notice of excavation.

Violation: 8-1-26-16(g)(prior) Failure to provide notice of excavation - damage occurred prior to two working days from request date.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Town Of Goodland Respondent: Other Party: **NIPSCO** Case No.: 4514 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation No Violation Recommended Penalty: whine Additional Information: APPROVED: 2 Rick Slagle (initialed)





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Town Of Goodland

UPPAC Database Record ID: 4514

Report Date: 4/26/2013

Investigator: Howard Friend

Damage Date: 1/30/2013

Damage Address: 319 N. James Street, Goodland, Newton

The Parties

Excavator: Town Of Goodland

Address: Po Box 269, 110 N Benton Street, Goodland, In 47948

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Drainage

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: No

Indiana 811 Ticket Number:

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation for a drain line.

Findings: Reported by Carrie Ludwig; excavator's response to initial notice was received on 4/22/2013. The excavator failed to provide notice of excavation prior to excavating with a backhoe.

Conclusion: There was a failure to provide notice of excavation.

Violation: 8-1-26-16(g) Failure to provide notice of excavation.

Committee Recommendation to IURC **Infrasource Underground Construction** Respondent: Other Party: **NIPSCO** Case No.: 4520 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation No Violation Recommended Penalty: Training Additional Information: APPROVED: Rick Slagle (initialed) Chairman

Underground Plant Protection Advisory

Indiana





http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Infrasource

UPPAC Database Record ID: 4520

Report Date: 4/26/2013

Investigator: Howard Friend

Damage Date: 1/31/2013

Damage Address: 7306 Taft Street, Merrillville, Lake

The Parties

Excavator: Infrasource

Address: 4033 E Morgan Rd, Ypsilanti, Mi 48197

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1301111549

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A natural gas service was damaged during excavation to install a gas line.

Findings: Reported by Carrie Ludwig (NIPSCo); excavator's response to initial notice was received on 4/21/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator reported the frost was twelve (12) inches deep and the gas line was nine (9) inches deep. They elected to use a backhoe to dig through the frozen ground rather than use hand tools to expose the facility.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.

Indiana Underground Plant Protection Advisory Committee Recommendation to IURC **Geiger Excavating** Respondent: Other Party: **NIPSCO** Case No.: 4526 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-16(g) Violation / No Violation Recommended Penalty: rainina Additional Information: APPROVED: (initialed) Rick Slagle

http://www.in.gov/iurc Office: (317) 232-2701 Facsimile; (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Geiger Excavating

UPPAC Database Record ID: 4526

Report Date: 4/26/2013

Investigator: Howard Friend

Damage Date: 2/5/2013

Damage Address: 749 N. Cedar Street, Auburn, Dekalb

The Parties

Excavator: Geiger Excavating

Address: 2808 W Coliseum Blvd., Fort Wayne, In 46804

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Trencher

Type of Work Performed: Sewer

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 4

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1302041727

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A two (2) inch natural gas line was damaged during excavation for a sewer line.

Findings: Reported by Carrie Ludwig (NIPSCo); excavator's response to initial notice was received on 4/18/2013. The excavator provided the original notice of excavation on January 15, 2013. They provided another notice of excavation on February 4, 2013. This is day number twenty (20) from the original notice. The gas line was damaged on February 5, 2013 this is the day before the second notice was good and twenty one (21) days after the first notice of excavation. The gas main was exposed in the excavation and the banks caved in causing the gas main to be pulled out of a mechanical fitting.

Conclusion: There was a failure to plan excavation to avoid damage. There was a failure to keep the notice of excavation active during excavation.

Violation: 8-1-26-16(g)(expire) Failure to provide notice of excavation - expired ticket.

8-1-26-20(a)(1) Failure to plan excavation to avoid damage or interference with underground facilities.

Underground Plant Protection Advisory Indiana Committee Recommendation to IURC Pin Point Directional Drilling Respondent: Other Party: **NIPSCO** Case No.: 4528 Date of Advisory Meeting: May 21, 2013 Statutes Allegedly Violated: IC 8-1-26-20(a)(2) Violation No Violation Recommended Penalty: arnina Additional Information: APPROVED: < Rick Slagle (initialed)



http://www.in.gov/iurc Office: (317) 232-2701 Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Pin Point Directional Drilling

UPPAC Database Record ID: 4528

Report Date: 4/25/2013

Investigator: Howard Friend

Damage Date: 2/21/2013

Damage Address: 2613 Caragana Ct, Goshen, Elkhart

The Parties

Excavator: Pin Point Directional Drilling

Address: 6200 W 800 N, Huntington, In 46750

Facility Owner: NIPSCO

Pipeline Facility

Facility Type: Natural Gas

Facility Function: Distribution

Type of Equipment: Directional Drilling

Type of Work Performed: Telecommunications

Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: False

Number of Customers Affected: 0

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$

Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes

Indiana 811 Ticket Number: 1302120712

Original Start Date:

Locate Instructions:

Follow-Up Locate Instructions (if applicable):

Synopsis: A three (3) inch natural gas main was damaged during a directional boring operation to install a telecommunications line.

Findings: Reported by Carrie Ludwig (NIPSCo); excavator's response to initial notice was received on 4/25/2013. The excavator had a valid locate request and the operator provided accurate locate markings. The excavator failed to expose the gas facility and therefore failed to maintain two (2) feet of clearance with mechanized equipment.

Conclusion: There was a failure to maintain clearance with mechanized equipment.

Violation: 8-1-26-20(a)(2) Failure to maintain two (2) feet clearance with mechanized equipment.